

[Next Unread Message](#)**View Message**

<b>Sent on</b>	07	19	2019	<b>Expires on</b>	08	07	2019
<b>From</b>	Parts and Service Division						
<b>Subject</b>	2016-19 ILX Driveshaft Inspection - Parts Return Instructions						

**PRIORITY/ACTION REQUIRED**

To: Acura Parts &amp; Service Managers

From: Warranty Parts Inspection

Dealers that replace driveshafts under Service Bulletin 19-035 will receive a Warranty Parts Return Request for return of both driveshafts to Raymond WPI.

Please note that this request applies to this Service Bulletin and the part numbers listed below only.

The return request will list one part number but notes "Please send driveshaft and half shaft". To satisfy the request, dealer MUST return the following parts:

- 44305-TV9-A01 Right Driveshaft Assembly
- 44500-TZ4-A01 Halfshaft Assembly (Intermediate Shaft)

The diagnostic process will identify if driveshafts are needed. Most vehicles will only need an inspection.

If you have questions about the return requirements, please contact the WPI Administrative Office at 937 642-2737.