ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager Freightliner Dealers – U.S. and Canada Western Star and Sterling Dealers – U.S. and Canada FCCC Dealers – U.S. and Canada Direct Warranty Customers – U.S. and Canada Thomas Built Buses Dealers – U.S. and Canada Export Distributors

Daimler Trucks North America LLC



REF #: ICI20-029 Effective: 09/14/2020

Release: 09/14/2020

SUBJECT: TBB FL818 – Revised Bulletin

This letter is to inform you that a revised bulletin for recall FL818, TBB Bendix Air Disc Brake Calipers, is available on DTNAConnect. Please print and use the revised bulletin for all work under FL818 from this point forward.

REVISION: A small number of replacement calipers for vehicles in FL818B may have a defect. For FL818B, an inspection of the replacement caliper has been added. (FL818A is **not** affected and inspection of replacement calipers for FL818A is **not** needed.) Previous repairs are **not** affected, as the issue is present at the time of installation.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC Link on DTNAConnect.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.