

Toyota Motor Sales, USA, Inc. 6565 Headquarters Drive Plano, TX 75024 (469) 292-4000

Original Publication Date: February 9, 2022

To: All Toyota Dealer Principals, General Managers, Service Managers, and Parts Managers

SAFETY RECALL RENOTIFICATION OWNER RENOTIFICATION 21R003

Toyota plans to send Safety Recall Follow-Up Notices for the campaigns referenced below to remind owners whose vehicles have not yet had campaign repairs completed.

Owner Renotification 21R003

Campaign	Model and Model Year	Approximate UIO	Renotification Schedule
J02	2013 Scion FR-S; Engine Valve Spring Replacement	9,300	Mid Feb 2022
KOF	2015 – 2017 Model Year Yaris - Front Seat Side and Curtain Shield Airbags May Not Deploy As Intended	23,200	
J05	2008-2019 Land Cruiser; Front Seatbelt	12,500	Mid to Late Mar 2022
JOS	2012 Avalon; Front Seat Belt Buckle Inspection and Replacement	6,400	
20TA01	1997-1998 MY Supra; 1998-1999 MY Celica; 1998 -2000 MY RAV4; 1998-1999 MY RAV4 EV - Airbag May Not Deploy Properly or Airbag Inflator May Rupture	128,200	
KOQ	2003-2008 Corolla; Passenger Airbag May Not Inflate Properly	99,600	

Thank you for your cooperation. TOYOTA MOTOR SALES, U.S.A., INC.