

# ◀ IMPORTANT UPDATE ▶

*The attached Dealer Letter has been updated. Refer to the details below.*

DATE	TOPIC
10/17/2019	<ul style="list-style-type: none"> <li>Recall expanded to include additional 2010 -2016 4Runner vehicles</li> <li>Recall expanded to include additional 2006 – 2013 Corolla vehicles</li> <li>Recall expanded to include additional 2009 – 2010 Matrix vehicles</li> <li>Recall expanded to include additional 2006 – 2007 Sequoia vehicles</li> <li>Recall expanded to include additional 2011 – 2013 Sienna vehicles</li> <li>Recall expanded to include additional 2006 Tundra vehicles</li> <li>Recall expanded to include additional 2007 – 2012 Yaris vehicles</li> <li>Recall expanded to include additional 2008 – 2012 Scion xB vehicles</li> <li>Recall expanded to include additional 2004 – 2005 RAV4 vehicles (<i>driver</i>)</li> <li>Opcodes and part number information has been updated</li> </ul>
09/25/2019	<ul style="list-style-type: none"> <li>The remedy op codes for Corolla, Tundra, and Sequoia have been changed.</li> <li>The op code labor times for Corolla, Tundra, and Sequoia have been corrected.</li> </ul>
08/28/2019	<ul style="list-style-type: none"> <li><u>The remedy has been suspended for 05-08 Matrix vehicles until further notice.</u></li> <li>A section on campaign phase interpretation has been added</li> <li>The “Parts Ordering Process” section has been updated with instruction on the part number that should be used to remedy 2005 Corolla vehicles.</li> <li>Instructions on inspecting airbag assemblies for 2005 – 2008 Matrix vehicles and 2003 – 2005 Corolla vehicles and the return process of these airbag assemblies have been added.</li> </ul>
5/09/2019	<ul style="list-style-type: none"> <li>Loaner Vehicle Reimbursement Procedure has been updated.</li> <li>A new section titled “Desiccated Service Modules”, has been added.</li> </ul>
12/12/2018	<ul style="list-style-type: none"> <li>Recall expanded to include 2003-2005 Corolla vehicles.</li> <li>Recall expanded to include 2003-2005 Tundra vehicles.</li> <li>Recall expanded to include 2002-2005 Sequoia vehicles.</li> <li>Opcodes and Part Number information has been updated.</li> <li>A new section titled “Unremedied VINs for Dealers” has been added for SOAR.</li> </ul>
07/17/2018	<ul style="list-style-type: none"> <li>Dealer Transportation Section added with new opcode and sublet for Customer Vehicle Pickup and Delivery.</li> <li>Part Numbers added in the Non-Desiccated Part Recovery section.</li> <li>Technician Training Requirements have been updated.</li> </ul>
2/20/2018	<ul style="list-style-type: none"> <li>Warranty Reimbursement Procedure section has been updated.</li> <li>Technical Training Requirements section has been updated to remove SC13B certification.</li> </ul>

*The most recent update in the attached Dealer Letter will be highlighted with a red box.*

Please review this notification with your staff to assure that all relevant personnel have been briefed regarding this subject.

Thank you for your cooperation.