

Attn: Slingshot Dealers

Subject: Safety Bulletin T-19-01 Released

Key Actions & Timing: Please Read

Questions: Contact Polaris Technical Service

Dear Slingshot Dealer,

Polaris Slingshot has determined that the vehicle's electrical current requirements may exceed the capability of the battery fuse block terminals under certain conditions. Excess current may lead to terminal damage, resulting in a loss of forward and rear lighting, instrument cluster, or power steering assist, which could increase the risk of a crash.

- Click [HERE](#) to view T-19-01
- Click [HERE](#) to view T-19-01 Dealer FAQs

Thank you for your attention.

Sincerely,

Polaris Service