



T680, T880, W990 Dana Forward Rear Axle Output Shaft


Author: Olin Frisvold

12/20/2019

Bulletin No.	22-016
Title (metadata)	22-016: T680, T880, W990 Dana Forward Rear Axle Output Shaft
Image	
What's New Abstract	Interim Campaign Notification – Chassis included in this bulletin may have an output shaft that was not correctly heat treated. As a result, the shaft may break. Dealers are instructed to hold these vehicles. This bulletin will be updated if additional chassis are added and when a repair path is finalized.
Section	Rear Axle - 22
Subject (on page & index)	T680, T880, W990 Dana Forward Rear Axle Output Shaft
Release Date	
Revision	
Condition	The output shaft may break or shear near the pinion nut.
Chassis Affected	95 chassis (83 U.S.; 12 Canada): T680, T880, and W990 Model Year 2020 vehicles built during 11/22/2019 through 12/05/2019 with Dana axles. See the attached chassis list for specific chassis.
Action	<p>Campaign</p> <p>Hold all affected chassis that enter your dealership even if the customer has no issue with the chassis.</p> <ol style="list-style-type: none"> 1. Review the attached chassis list for your dealer code. 2. Hold all vehicles found at your dealership. <div style="border: 1px solid black; padding: 2px; margin-top: 5px;">  NOTE </div>

T680, T880, W990 Dana Forward Rear Axle Output Shaft

22-016

	<p>Some affected chassis are new and Kenworth may not have the customers' names or addresses registered. Please contact your customers or check your lot for these chassis.</p> <p> CAUTION</p> <p>Dealers may face liability for progressive damage if they release affected chassis without performing the repairs described herein or obtaining the customer's informed consent to delay or forego the repair.</p>
Warranty	
Parts	
Background	
Procedure	
Attachments	Dealer\Chassis List