



Indian Motorcycle Company
P.O. Box 47700
Medina, MN 55340-9960

IMPORTANT SAFETY RECALL
This notice applies to your vehicle

Recall Campaign: 19E007
Subject: 2015-2019 Indian Scout / Sixty /
Bobber Motorcycles equipped with the
Black Clutch and Brake Lever Accessory Kit
(pn 2883795-658)

PLEASE READ IMMEDIATELY

VIN I-19-01

FIRST NAME LAST NAME
ADDRESS
CITY, ST ZIP

Dear Indian Motorcycle Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Indian Motorcycle has decided that a defect which relates to motor vehicle safety exists in some 2015-2019 Scout / Sixty / Bobber Motorcycles equipped with the Black Clutch and Brake Lever Accessory Kit (pn 2883795-658). Our records indicate you have purchased a potentially affected vehicle.

The reason for this recall:

Indian Motorcycle has identified a potential assembly concern affecting the black Clutch and Brake Lever Accessory Kit (PN: 2883795-658), for use with Indian Scout, Scout Sixty and Bobber models. This affects the brake lever portion of the kit, which may not have been assembled to specification. The free-play adjustment screw may not be correctly installed and can result in front brake drag, unintentional front brake application, and potentially locking of the front wheel, increasing the risk of a crash.

What Indian Motorcycle and your dealer will do:

Indian Motorcycle will issue a Safety Bulletin to all Indian Motorcycle dealers, with instructions required to replace the brake lever. Repairs will be made by any authorized Indian Motorcycle dealers at no cost to you. The time needed for this repair is approximately 18 minutes.

What you should do:

Contact your authorized Indian Motorcycle dealer to schedule an appointment to have the bulletin repair performed. Do not attempt repairs yourself. Repairs must be done only by an authorized Indian Motorcycle dealer.

If you have questions or if you need more information:

While your Indian Motorcycle dealer is in the best position to answer your questions, if you have any questions that your dealer cannot address, if you are having difficulty obtaining the repair outlined in this letter, or if you need assistance finding an Indian Motorcycle dealer, please visit our website at <http://www.indianmotorcycle.com> or contact our Indian Motorcycle Customer Connections Department by calling 1-877-204-3697.

If you believe that the dealer or Indian Motorcycle has failed or is unable to remedy the defect within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E., Washington, D.C. 20590, or call the toll free Vehicle Safety Hot Line at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

This notice was mailed to you according to our most current registration information. If you no longer own your Indian Motorcycle, please contact your local Indian Motorcycle dealer to have the ownership information changed. The Indian Motorcycle Consumer Service Department cannot change ownership information without identification. Federal law requires that any vehicle lessor receiving this notice must forward a copy of this notice to the lessee within 10 days.

Please accept our apologies for any inconvenience this may cause you. Your safety and continued satisfaction with your Indian Motorcycle is our primary concern. Thank you for your prompt attention to this matter.

Sincerely,
Indian Motorcycle Company