



Indian Motorcycle
Company
P.O. Box 47700
Medina, MN 55340-9960

IMPORTANT SAFETY NOTICE
This notice applies to your vehicle

Recall Campaign: **19V-339**
Subject: **2014 Indian Motorcycle (111 c.i.) Forward Lighting**
PLEASE READ IMMEDIATELY

VIN: I-19-02
First Name Last Name
Address
City, State ZIP

Dear Indian Motorcycle Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Indian Motorcycle has decided that a defect which relates to motor vehicle safety exists in certain 2014 Indian Motorcycles (111 c.i.). This is to inform you that your vehicle could contain a defect that could affect safe operation. Our records show you have purchased an affected vehicle.

The reason for this notice:

Indian Motorcycle has determined that all model year 2014 111 c.i. motorcycles may experience loss of forward lighting. If this event does occur, the High Beam indicator will flash on the gauge cluster. If the motorcycle lighting malfunctions while in operation, it may reduce visibility and increase the risk of a crash.

What you should do:

Contact your authorized Indian Motorcycle dealer to schedule an appointment to have the repairs performed. Do not attempt repairs yourself. Repairs must be done only by an authorized Indian Motorcycle dealer. This repair should take approximately 60 minutes. When making contact with your dealer, discuss parts availability, their schedule and how long they will need to keep your vehicle.

What your dealership will do:

To address this concern, Indian Motorcycle has authorized your dealer to inspect the VCM connector and update the VCM software. If the VCM connector is damaged, a new connector and VCM will be installed. This work will be performed by your dealer at no cost to you.

This notice was mailed to you according to our most current registration information. If you no longer own this vehicle, or if some of the contact information in this notice is incorrect, please contact your dealer to complete a transfer of ownership. Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.

If you need assistance contacting or locating an Indian Motorcycle dealer, or if you have questions your Indian Motorcycle dealer is not able to address, contact our Indian Motorcycle Owner Connections Department at 1-877-204-3697, scan the QR code, or go to <https://www.indianmotorcycle.com/en-us/self-help/>.



If you believe that Indian Motorcycle has failed to remedy this defect without charge or is unable to do so within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE., Washington, D.C. 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or on the web go to www.safercar.gov.

We apologize for this inconvenience and assure you that we are committed to customer satisfaction and providing world-class products for riders to enjoy.

Sincerely,

Indian Motorcycle Company

For the latest updates to this safety recall, or to check if your vehicle is part of another safety recall, scan the QR code, or go to www.polaris.com/en-us/on-road-recalls/.

