



Safety Notice

Affected Models	VT17, VT20, and VT24 trailers built prior to February 2019
Attention	Dealership Owners, Managers, Parts and Service Managers
What Dealer Should Do	<ol style="list-style-type: none">1. Read the attached customer notice.2. Check safety notification search tool on Dealer Central to see a list of units in your area.3. Order one kit for each affected trailer in your area.4. Install kit using instructions below5. Submit warranty claim under trailer VIN, not HX machine serial number.
Parts Required	Kit #190-2483
Estimated Repair Time	1 hour
Compensation	Labor, Mileage, and Parts
Dealership Notes	<p>URGENT: Please perform this update as soon as possible in the interest of safety. Ditch Witch requests that you update all machines in your area by 12/31/2019.</p> <p>A notification will be mailed to owners of affected models in one week. Please note "What You Should Do" section of the attached customer notice. If you have any questions, contact the Trencher/Trenchless/Electronics Product Support Group.</p>

Instructions

1. Check trailer serial number. Replace trailer lunette mounting hardware (bolts and locknuts) if serial number indicates trailer was manufactured before February 2019.

IMPORTANT: Bolt is p/n 105-2317 and locknut is p/n 105-953. See parts page ID0466871.

2. Tighten new trailer lunette hardware to 320ft•lb.