

2016 MX-5 Undercover welding Concern Safety Recall 3619F

A. VEHICLE INSPECTION PROCEDURE

1. Verify that the vehicle is within the following ranges:


Model	Subject VIN range	Subject build date range
2016MY MX-5	JM1ND**** G0 100680 - 103315	From May 26,2015 through July 6,2015

The asterisk symbol "*" can be any letter or number.

- If the vehicle is within the above ranges, proceed to Step 2.
- If the vehicle is not within the above ranges, return vehicle to the customer or inventory.

2. Perform a Warranty Vehicle Inquiry using your eMDCS System and inspect vehicle for Campaign Labels **Recalls 3619F** attached to the vehicle's hood or bulkhead. Refer to eMDCS System - Warranty Vehicle Inquiry Results table below.

NOTE: Be sure to verify Recall number as the vehicle may have multiple Recall labels.




eMDCS System - Warranty Vehicle Inquiry Results:

If eMDCS displays:	Campaign Label is:	Action to perform:
RECALL 3619F OPEN	Present	Contact the Warranty Hotline at (877) 727-6626 option 3 to update vehicle history.
	Not present	Proceed to "B. REPAIR PROCEDURE".
RECALL 3619F CLOSED	Present	Return vehicle to inventory or customer.
	Not present	Proceed to "C. CAMPAIGN LABEL INSTALLATION".
RECALL 3619F IS NOT PRESENT	Does not apply	Recall does not apply to this vehicle. Return vehicle to inventory or customer.

B. REPAIR PROCEDURE: Front cross member under cover Removal/Installation

ACTION TO BE TAKEN

1. Lift up the vehicle.
2. Remove bolts.



3. Remove the front cross member under cover.
4. Install new under cover in the reverse order of removal.

C. CAMPAIGN LABEL INSTALLATION

1. Fill out a blue "Campaign Label" (9999-95-065A-06) with Campaign No: "3619F", your dealer code, today's date.

CAMPAIGN LABEL	
CAMPAIGN NO: _	
DEALER CODE: _____	
DATE: // //	

P/N 9999-95-065A-06

Affix it to the hood or bulkhead as shown:

