



GM/Chevy 4500 Chassis Recall

Seatbelt unfastened telltale indicator

Bulletin Type:	RECALL	Publication Date:	October 2019
RECALL #:	19V-690	Make:	Jayco
Job Code(s):	NA	Model:	Redhawk SE
Flat Rate(s):	NA	Model Years:	2019-2020

Incident:	GM/Chevy chassis recall – The Seatbelt telltale will not illuminate for approx. 5 seconds, after the ignition is moved to the on and start position. The instrument panel cluster (IPC) requires reprogramming.
Affected Units:	2019 Redhawk SE K1GA0196-0244 K1GJ0199-0248 K1GN0089-0140 2020 Redhawk SE L1GA0051-0141 L1GJ0051-0169 L1GN0065-0107

INSTRUCTIONS

A GM/Chevy Service Center will reprogram the instrument panel cluster at no cost to current owner.

You can locate the closest dealer through Chevy's website <https://www.chevrolet.com/dealer-locator>.

Jayco's sole obligation under our limited warranty is to repair or replace defective materials and/or workmanship deemed our responsibility as determined by Jayco in our sole discretion. Jayco reserves the right to use new and/or remanufactured parts or materials of similar quality to complete any work, and to make parts and/or design changes as appropriate without notice to anyone. Jayco designs and/or materials changes are done without obligation to incorporate such changes in previously manufactured product. Jayco makes every reasonable effort to ensure field remedies will not adversely affect performance and/or safety of the unit. This field remedy is not intended to extend to future performance of this RV, or any of its materials, components or parts beyond the standard warranty period. The RV owner's obligation to notify Jayco, or one of its independent, authorized dealers, of a claimed defect does not modify any obligation placed on the RV owner to contact Jayco directly when attempting to pursue remedies under state or federal law. Jan. 2019.

903 South Main Street • P.O. Box 460 • Middlebury, IN 46540