



Service Bulletin American Honda Motor Co., Inc.

SAFETY RECALL

2019 CRF450L HORN STAY BROKEN

Honda is launching a SAFETY RECALL on **ALL** 2019 CRF450L motorcycles to replace the horn assembly. Under certain conditions, the horn stay can break causing the horn to become loose or fall off.

Effective immediately, you **MUST NOT SELL** any affected **NEW or USED** 2019 CRF450L motorcycle until it is repaired according to the associated Service Bulletin.

AFFECTED UNITS

2019 CRF450L - ALL

To manage your affected inventory, use eResponsibility Report.

SERVICE BULLETIN

Service Bulletin CRF450L #1, which will include the repair procedure, parts information, and warranty claim information, will be posted early-October.

PARTS INFORMATION

Parts will be available on open order.

CUSTOMER NOTIFICATION

AHM intends to mail customer notification letters as early as possible, subject to regulatory agency approval.

Make sure all departments in your dealership are aware of this action.

Honda will update dealers with any new information as it becomes available.

If you have any questions, please contact TechLine or your District Service Manager.

1 of 1