



Campaign No. 2020020014, February 2020

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model GLC-Class (253 platform)**
Model Year 2019
Airbag Warning Labels

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that certain Model Year ("MY")19 GLC-Class (253 platform) vehicles could be equipped with incorrect country variants of the airbag warning labels on the outside/inside of the passenger side sun visor. In such case, the airbag warning labels in affected vehicles may not meet local requirements. All the labels installed include pictograms indicating the proper use of a child seat but the accompanying explanations might not be in the local language. If a sun visor label is in a foreign language, an occupant may not be aware of the risks a deploying airbag may pose to children sitting in the front seat, potentially increasing the risk of injury in the event of a crash. An authorized Mercedes-Benz dealer will check the airbag warning labels on the passenger side sun visor of the affected vehicles and replace the sun visor incl. warning label, as necessary.

Prior to performing this Recall Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired. Always Check VMI for any open campaigns, and perform accordingly.
- **VMI must always be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.**
- Please review the entire Recall Campaign bulletin and follow the repair procedure exactly as described.

Please note that Recall Campaigns **do not expire** and may also be performed on a vehicle with a vehicle status indicator.

Approximately 10041 vehicles are involved.

Order No. P-RC-2020020014

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Check/test procedure

1. Check airbag information labels on front passenger sun visor to make sure US/English version is correct.



Incorrect versions may have been applied.



The information labels are applied on the inner side and outer side of the front passenger sun visor.(Figure1)




Figure 1

Specified airbag information label below is correct for the US/English version: The airbag information label must match this to be correct.



USA SUV

- A. **Incorrect** version of airbag information label applied: Carry out **work procedure**.
- B. **Correct** US/English version of airbag information label applied: **End measure**.

Work procedure

1. Replace sun visor (**AR68.60-P-5480NKB**) airbag information label is attached.



It is not possible to remove just the airbag information label from the sun visor, as the information label is part of the sun visor. The sun visor must be replaced.

Primary Parts Information

Qty.	Part Name	Part Number
1	sun visor	*

*The replacement parts must be determined according to the VIN via XPPI.

Warranty Information**With check**

Operation: Check airbag information label on front passenger sun visor (02-1439)

Damage Code	Operation Number	Labor Time (hrs.)
58 916 04 8	02-1439	0.1

With check and replace

Operation: Check airbag information label on front passenger sun visor (02-1439)
Replace sun visor and information label (02-1440)

Damage Code	Operation Number	Labor Time (hrs.)
58 916 04 7	02-1439	0.1
	02-1440	0.2

**Note**

Operation Number labor times are subject to change.