

URGENT SAFETY RECALL NOTICE

I-19-02 2014 Indian Motorcycles (111ci) Forward Lighting



Operating your motorcycle without having this recall performed may increase a safety risk to riders.

Contact your Indian Motorcycle dealership immediately

ND NOTIFICATION CTION REQUIRED!

Indian Motorcycle Company 2100 Highway 55 Medina MN 55370 This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. You are being sent this notification because our records indicate you have not had this recall completed.

The reason for this recall:

Indian Motorcycle has determined that some 2014 111ci motorcycles may experience loss of forward lighting. If this event does occur, the High Beam indicator will flash on the gauge cluster. If the motorcycle lighting malfunctions while in operation, it may reduce visibility and increase the risk of a crash.

What you should do:

Contact your authorized Indian Motorcycle Dealer to schedule an appointment to have the repairs performed. Do not attempt repairs yourself. Repairs must be done only by an authorized Indian Motorcycle dealer. This repair should take approximately 60 minutes. When making contact with your dealer, discuss parts availability, their schedule and how long they will need to keep your vehicle.

What your dealership will do:

To address this concern, Indian Motorcycle has authorized your dealer to inspect the VCM connector and update the VCM software. If the VCM connector is damaged, a new connector and VCM will be installed. This work will be performed by your dealer at no cost to you.

This notice was mailed to you according to our most current registration information. If you no longer own this vehicle, or if some of the contact information in this notice is incorrect, please contact your local Indian Motorcycle dealer to complete a transfer of ownership. Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.

If you need assistance contacting or locating an Indian Motorcycle dealer, or if you have questions your Indian Motorcycle dealer is not able to address, you may contact our Indian Motorcycle Owner Connections Department at 1-877-204-3697, scan the QR code, or go to www.indianmotorcycle.com/en-us/self-help/email/



If you believe that Indian Motorcycle has failed to remedy this defect without charge or is unable to do so within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE., Washington, D.C. 20590; or call the toll-free Vehicle Safety Hotline

at 1-888-327-4236 (TTY: 1-800-424-9153); or on the web go to www.safercar.gov.

We apologize for this inconvenience and assure you that we are committed to customer satisfaction and providing world class products for riders to enjoy.

Sincerely,

Indian Motorcycle Company

For the latest updates to this safety recall, or to check if your vehicle is part of another safety recall, scan the QR code, or go to www.indianmotorcycle.com/en-us/vin-search/

