



Ford Motor Company  
Ford Customer Service Division  
P.O. Box 1904  
Dearborn, Michigan 48121 1904



0000221 01 / 000000217 / 12



April 2023



**\* \* \* IMPORTANT SAFETY RECALL REMINDER \* \* \***

According to our records, your 2019 F-350 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**KEY INFORMATION**

- Your vehicle is involved in an important safety recall
- Your safety is important to us. Schedule an appointment to have service procedure completed
- This procedure will be performed free of charge

**Recall Number 19S31 - Rear Axle Shaft Material and Description:**

**What is the Issue?** On your vehicle, it may be possible that the material composition of the passenger side rear axle shaft is incorrect and does not meet Ford's specifications.

The passenger side rear axle shaft may fracture. This can subsequently result in a loss of drive power and the inability to hold the park function. **If the parking brake is not applied, this could result in unintended vehicle movement or rollaway, increasing the risk of injury or crash.**

**Recall Number 19C10 - High Series LED Headlamps and Description:**

**What is the Issue?** On your vehicle, the Daytime Running Lamps (DRLs) do not dim when the headlamp switch is moved into the on position.

This may result in a higher than permitted lighting output when the headlamps are on, which may reduce the visibility of other drivers, increasing the risk of a crash.

**What Are We Asking You To Do?** Please contact your dealer to schedule an appointment to have these important service procedures completed. If you do not already have a servicing dealer, you can access [ford.com/support](http://ford.com/support) for dealer addresses, maps and driving instructions.

The vehicle owner is responsible for having these service actions performed. Ford Motor Company reserves the right to deny coverage for any vehicle damage that may result from failure to have these recalls performed on a timely basis. Therefore, please have this recall performed as soon as possible.

**Service Assistance:** If you have additional questions, please contact the Ford Motor Company Customer Relationship Center at 1-866-436-7332 and one of our representatives will be happy to assist you. For the hearing impaired call 1-800-232-5952 (TDD). Office Hours are Monday through Friday: 8:00AM - 5:00PM (Your Local Time).

If you wish to contact us through the Internet, our address is: [ford.com/support](https://ford.com/support).

If your authorized dealer has recently completed these recall repairs, please disregard this reminder.

We apologize for any inconvenience this may cause and want to assure you that, with your assistance, we will correct these conditions. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

Thank you for your attention to these important matters.

Ford Customer Service Division



Ford Motor Company  
 División de Servicio al Cliente de Ford  
 P. O. Box 1904  
 Dearborn, Michigan 48121



0000221 01 / 000000217 / 12



Abril de 2023



**\*\*\* RECORDATORIO DE CAMPAÑA DE SEGURIDAD IMPORTANTE \*\*\***

Según nuestros registros, en su 2019 F-350 Ford Truck no se han realizado las reparaciones necesarias correspondientes a esta campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**INFORMACIÓN CLAVE**

- Su vehículo ha sido incluido en una importante campaña de seguridad.
- Su seguridad es muy importante para nosotros. Programe una cita para completar el procedimiento de servicio.
- Este procedimiento se llevará a cabo sin costo alguno.
- *Si necesita ayuda o tiene alguna pregunta, por favor llame al Centro de Relación con Clientes al 1-866-436-7332 y presione 2 para Español.*

**Número y descripción de la campaña:**

**19S31 - Material de la semiflecha trasera**

**¿Cuál es el problema?**

Es posible que la composición del material de la flecha del eje trasero del lado del pasajero sea incorrecto y no cumpla con las especificaciones de Ford.

La flecha del eje trasero del lado del pasajero se podría fracturar. Posteriormente esto se podría traducir en una pérdida de potencia de impulsión y la incapacidad de sostener la función de estacionamiento. **Si no se aplica el freno de estacionamiento, se podría producir un movimiento o desplazamiento no intencionado del vehículo, lo cual aumenta el riesgo de lesiones o choque.**

**Número y descripción de la campaña:**

**19C10 - Faros LED Serie Alta**

**¿Cuál es el problema?**

Las luces de conducción diurna (DRL) de su vehículo no se atenúan cuando el interruptor de los faros se mueve a la posición de activación.

Esto se podría traducir en una potencia de salida de luz superior a la permitida cuando los faros están encendidos, lo cual podría reducir la visibilidad de otros conductores y aumentar el riesgo de choque.

**¿Qué le solicitamos hacer?**

Comuníquese con su distribuidor a fin de programar una cita para llevar a cabo este importante procedimiento de servicio. Si aún no tiene un distribuidor para realizar el servicio, puede acceder a [ford.com/support](https://ford.com/support) para conocer las direcciones de los distribuidores, ver mapas y obtener las instrucciones para llegar.

El propietario del vehículo es responsable de realizar estas acciones de servicio. Ford Motor Company se reserva el derecho de negar la cobertura en caso de que el vehículo hubiese sufrido daños por no haber realizado la campaña de manera oportuna. Por lo tanto, le solicitamos que realice esta campaña lo antes posible.

**Servicio de asistencia:**

Si tiene preguntas, comuníquese con el Centro de Relación con Clientes de Ford Motor Company al 1-866-436-7332 y uno de nuestros representantes con gusto lo atenderá. Las personas con problemas de audición pueden llamar al 1-800-232-5952 (TDD). El horario de atención es de lunes a viernes, de 8:00 a.m. a 5:00 p.m. (hora local).

Si desea comunicarse con nosotros a través de Internet, nuestra dirección es: [ford.com/support](https://ford.com/support).

Si ya realizó esta reparación en su distribuidor autorizado, ignore este aviso.

Lamentamos cualquier inconveniente causado y deseamos asegurarle que, con su ayuda, corregiremos el problema. Nuestro compromiso, junto con el de su distribuidor, es ofrecerle servicio y apoyo de alto nivel.

Gracias por su atención en este asunto sumamente importante.

Ford, División de Servicio al Cliente