



**SLINGSHOT®**

# URGENT SAFETY RECALL NOTICE

T-19-01 2015-2019 Slingshot / SL / SLR / GT  
BATTERY FUSE BLOCK INSPECTION & CHASSIS  
FUSE RELOCATION



Operating your vehicle without having this recall performed may increase a safety risk to riders.

Contact your Slingshot  
dealership immediately

Slingshot Division  
Polaris Inc.  
P.O. Box 47700  
Medina, MN 55340

2ND NOTIFICATION  
ACTION REQUIRED!



This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. You are being sent this notification because our records indicate you have not had this recall completed.

The reason for this recall:

Polaris Slingshot has decided that the vehicle's electrical current requirements may exceed the capability of the battery fuse block terminals under certain conditions. Excess current may lead to terminal damage, resulting in a loss of forward and rear lighting, instrument cluster, or power steering assist, which could increase the risk of a crash.

What you should do:

To minimize risk to your safety, please contact your authorized Slingshot dealer as soon as possible to schedule an appointment to have the repairs performed. Do not attempt repairs yourself. Repairs must be done only by an authorized Slingshot dealer. The repair may take approximately 30 minutes. When making contact with your dealer, discuss parts availability, their schedule and how long they will need to keep your vehicle.

What your dealership will do:

Slingshot has issued a Safety Recall to all Slingshot dealers, with the appropriate instructions to inspect the Battery Fuse Block terminals and relocate the chassis fuse. Repairs will be made at an authorized Slingshot dealer at no cost to you.

This notice was mailed to you according to our most current registration information. If you no longer own this vehicle, or if some of the contact information in this notice is incorrect, please contact your local Slingshot dealer to complete a transfer of ownership. Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.

If you need assistance contacting or locating a Slingshot dealer, or if you have questions your Slingshot dealer is not able to address, you may contact our Polaris Owner Connections Department at 1-855-863-2284, scan the QR code, or go to [www.polaris.com/en-us/contact/](http://www.polaris.com/en-us/contact/).



If you believe that the Slingshot Division of Polaris Inc. has failed to remedy this defect without charge or is unable to do so within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE., Washington, D.C. 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or on the web go to [www.safercar.gov](http://www.safercar.gov).

We apologize for this inconvenience and assure you that we are committed to customer satisfaction and providing world class products for riders to enjoy.

Sincerely,

Polaris On-Road Vehicles

For the latest updates to this safety recall, or to check if your vehicle is part of another safety recall, scan the QR code, or go to [www.polaris.com/en-us/on-road-recalls/](http://www.polaris.com/en-us/on-road-recalls/).

