



March, 2020

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2020 F-150 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number 19S40 - B+ EYELET ADHESIVE OBSTRUCTION and Description:**

**What is the issue?** On your vehicle, the positive battery terminal fastener, which connects several wires to the battery, may not be properly secured due to an obstruction of wiring adhesive between the terminal eyelets.

This may result in intermittent or inoperative vehicle systems affecting instrument panel displays, braking or steering control and could cause engine stalling. These conditions may increase the risk of a crash. A positive battery terminal fastener that is not properly secured may also create an electrical short, increasing the potential for smoke, melting, or risk of fire.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [www.Fordowner.com](http://www.Fordowner.com).

Thank you for your attention to this very important matter.

Marzo de, 2020

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2020 F-150 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña: 19S40 - OBSTRUCCIÓN DEL ADHESIVO DE LOS OJALES B+**

**¿Cuál es el problema?** En su vehículo, el sujetador del terminal positivo de la batería, el cual conecta varios cables a la batería, podría no estar correctamente asegurado debido a una obstrucción del adhesivo del cableado entre los ojales del terminal.

Esto podría ocasionar un funcionamiento intermitente o el no funcionamiento de los sistemas del vehículo, lo cual afecta las pantallas del panel de instrumentos, el control de frenos o dirección y podría provocar un paro del motor. Estas condiciones podrían aumentar el riesgo de choque. Si un sujetador del terminal positivo de la batería no se ha asegurado correctamente también podría generar un cortocircuito eléctrico, lo cual aumenta el riesgo de humo, fundición o incendio.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [www.Fordowner.com](http://www.Fordowner.com).

Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

C / 0549 / 00000000000108 / A



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

