



May, 2022

**\* \* \* IMPORTANT SAFETY RECALL REMINDER \* \* \***

According to our records, your 2019 F-550 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number** 19S52 - CARPET SHIELDING AND INSULATION REWORK  
**and Description:**

**What is the issue?** If your vehicle is involved in a crash, deployment of the front seatbelt pretensioners may cause a fire inside the driver or passenger side B-pillar trim (the outboard floor area next to the front seats) in the vehicle passenger compartment.

A fire in the B-pillar area may spread within the vehicle and increase the risk of injury. You may notice odor and/or smoke as the fire develops.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [ford.com/support](http://ford.com/support).

Thank you for your attention to this very important matter.

Mayo de, 2022

**\* \* \* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \* \* \***

SegUR nuestros registros, no se realizaron en sur 2019 F-550 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** 19S52 - REACONDICIONAMIENTO DE PROTECCIÓN Y AISLAMIENTO DE LA ALFOMBRA

**¿Cuál es el problema?** Si su vehículo participa en un choque, el despliegue de los pretensores de los cinturones de seguridad delanteros podrían ocasionar un incendio en el interior de la vestidura del pilar B del lado del conductor o del pasajero (área del piso externo junto a los asientos delanteros) en el compartimiento de pasajeros.

Un incendio en el área del pilar B podría propagarse dentro del vehículo y aumentar el riesgo de sufrir lesiones. Podría percibir olor y/o humo mientras se desarrolla el fuego.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [ford.com/support](http://ford.com/support).

Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0000909 A / 000000000000047 / 47



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

