



July, 2021

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2010 MKZ has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number and Description:** **19S54 - ABS HCU VALVE CONCERN (17X29)**

**What is the issue?** On your vehicle, a chemical reaction between aged DOT 3 brake fluid and the zinc plating inside the Hydraulic Control Unit (HCU) may result in a gel formation, which may cause the HCU valve to be stuck open.

If the HCU valve is stuck open, this may result in extended brake pedal travel required to stop the vehicle, increasing the risk of a crash. The condition does not result in a loss of braking function and the vehicle can be brought to a controlled stop.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [owner.lincoln.com](http://owner.lincoln.com).

Thank you for your attention to this very important matter.

Julio de, 2021

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2010 MKZ las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** **19S54 - PROBLEMA DE LA VÁLVULA HCU DE ABS (17X29)**

**¿Cuál es el problema?** En su vehículo, una reacción química entre el líquido de frenos DOT 3 antiguo y el recubrimiento de cinc en el interior de la unidad de control hidráulico (HCU) podrían provocar una formación de gel, la cual podría generar el atoramiento en apertura de la válvula de HCU.

Si la válvula de HCU se atora abierta, se podría requerir un mayor recorrido del pedal del freno para detener el vehículo, lo cual aumenta el riesgo de choque. Esta condición no provoca una pérdida de la función de frenado y el vehículo se puede detener de forma controlada.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [owner.lincoln.com](http://owner.lincoln.com).

Gracias por su atención en este asunto sumamente importante.



THE LINCOLN MOTOR COMPANY

P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

A / 0001 / 000000000000001 / A



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

