



IMPORTANT SAFETY RECALL NOTICE

7/18/2019

Subject: Potential for loose upper shock mount on
Fire Truck Independent Front Suspensions

Reyco Granning LLC has decided that a defect which relates to motor vehicle safety exists in Fire Truck Independent Front Suspension (FT IFS) modules manufactured by Reyco Granning from December 01, 2014 to July 01, 2019.

What is the issue?

Reyco Granning has learned that FT IFS modules manufactured during the affected timeframe could have loose upper shock joints. If loose upper shock joints are not detected, they may eventually separate from their mating part, which could result in collateral damage including loss of steering assist. Reyco Granning has notified NHTSA of this condition. This recall notice applies to FT IFS modules which have been identified as being purchased from Reyco Granning by your company within the timeframe listed above. A list of the serial numbers of FT IFS modules manufactured within the affected timeframe and sold by Reyco Granning to your company is attached as Exhibit A in the individual OEM letter of notification.

What are we asking your company to do?

Reyco Granning recommends that impacted OEMs conduct their own safety-related defect determination with respect to the vehicles in which the affected FT IFS units were installed, and that the impacted OEM file its own defect information report with NHTSA under 49 CFR Sections 573.3(f) and 573.6.

We also recommend that impacted OEMs conduct a recall of the vehicles in which it installed affected FT IFS units, so that they can have the hardware in the upper shock pocket replaced. Inspection and repair procedures are described in the attached Service Bulletin.

What will we do?

Reyco Granning will support the inspection and repair effort as set forth in the attached Service Bulletin, and is ready to begin that support immediately. Please review the Service Bulletin attached to this letter, which addresses:

- Proper Correction Method
- Authorized Labor Allocation
- Inspection Tools Required
- Repair Tools Required
- Inspection and Repair Instructions

As you are aware, it is a violation of Federal law to deliver any of the FT IFS modules covered by this recall notice, or vehicles incorporating such modules, under a sale or lease until the identified defect is remedied.

Thank you for your prompt attention regarding this important matter. Please contact me at (417) 461-4762 with any questions or concerns.

Sincerely,
Will Seeger
VP Sales

EXHIBIT A

Affected E-One Serial Numbers:

2006206	2020684
2006986	2021920
2006640	2022633
2007461	2022640
2007462	2022594
2007400	2022942
2007319	2022987
2007893	2022989
2009238	2018650
2009018	2023064
2010194	
2010003	
2011150	
2011124	
2011557	
2011564	
2011045	
2012175	
2012166	
2011012	
2010860	
2010868	
2013822	
2014962	
2015113	
2015392	
2016118	
2016060	
2016372	
2017390	
2017451	
2018401	
2017196	
2017189	
2017994	
2018491	
2018660	
2020396	
2020979	