

**Amended Defect Information Report**

(Section 573.6)

***FL-809*****Date of Submission:** *March 8<sup>th</sup>, 2019***Manufacturer:** Daimler Trucks North America LLC  
P.O. BOX 3849  
Portland, Oregon 97208**Type of Report:**       **Safety Defect**                       **Non-Compliance****Vehicle Information****Model Yr. Start:**                      *2019*                      **Model Yr. End:** *2019***Make:** *Freightliner Custom Chassis***Model:** *S2RV Chassis Cab***Production Dates:**    **Begin:** *10/05/2018***End:** *12/18/2018***Descriptive Information:***Certain chassis cab vehicles within the build range, built without ABS module***Number potentially involved:** *0*      **Estimated percentage of involve with defect:** *0%***Defect / Noncompliance Description****For this Defect/Noncompliance:****Describe the defect or noncompliance:***On the affected vehicle chassis, the ABS modules may not have been installed as required by FMVSS 121 S5.1.6.***If a noncompliance, provide the applicable FMVSS:** *FMVSS 121 S5.1.6* **Check if this recall only affects products in certain geographic regions.****Describe the safety risk:***The operator may not be aware of the absence of ABS function. Unknowingly operating the vehicle without ABS function may increase risk of a crash.*

## **Chronology of Defect / Noncompliance Determination**

**Provide the chronology of events leading up to the defect decision or test data for the noncompliance decision:**

*On January 7<sup>th</sup>, 2019 Freightliner Custom Chassis was advised by our transporting contractor of ABS lamp malfunction due to ABS module omission, while completed vehicles were being transferred from our plant to the customers. DTNA began investigation to understand scope of issue. Early February 2019 DTNA began field inspection of vehicles within the impacted population exposure. February 2019, with an abundance of caution, DTNA decided to initiate a voluntary recall.*

*March 2019 subsequent to this recall filling, DTNA determined that the vehicles originally included in this recall had the ABS module installed and therefore, do not need to be repaired under this recall.*

## **Identify the Remedy**

**Describe the defect/noncompliance remedy program, including the manufacture's plan for reimbursement.**

*None, vehicles do not require repair*

## **Identify the Recall Schedule**

**Describe the recall schedule for notifications:**

*None*

<b>Planned Dealer Notification Begin Date:</b>	<i>04/27/2019</i>
<b>Planned Dealer Notification End Date:</b>	<i>04/27/2019</i>
<b>Planned Owner Notification Begin Date:</b>	<i>04/27/2019</i>
<b>Planned Owner Notification End Date:</b>	<i>04/27/2019</i>

**Manufacture's identification code for this recall (if applicable):** *FL-809*

## **DTNA Representative**



Andy Jones  
Manager  
Compliance and Regulatory Affairs