

# 2014-2015 MY F-TYPE Safety Recall H208

## Incorrect wiring on the Seatbelt Tension Sensor Harness Connector



- Certain F-TYPE 2014 and 2015 model year vehicles, previously remedied in recall J047, may have had a seat belt service part installed containing the same defect as the parts from the original recall.
- Due to a catalogue error, Service replacement seat belts may not have been correctly wired which can result in the front passenger air bag remaining activated, even when a child restraint is placed in the front passenger seat or a small statured adult occupies that seat. In the event of a crash the seat occupant may be at an increased risk of injury.
- All affected vehicles will be inspected and if required the seat belt tension harness wiring will be modified.
- 7060 USA and 816 Canadian vehicles will require inspection. Of these approx 125 vehicles may require a wiring modification.
- Recall defect reports submitted to NHTSA and TC April 25<sup>th</sup> 2019
- Retailer Notification Bulletin May 9<sup>th</sup> 2019. Technical bulletin expected by w/c May 13<sup>th</sup> 2019
- Customer mailing notification before June 21<sup>st</sup> 2019. All affected vehicles have been retailed.