

SAFETY RECALL LAUNCH STATUS

N333 & N336



RECALL N333 - DRIVER SEAT BELT EMERGENCY LOCKING RETRACTOR	
AFFECTED MODELS	- 16&17 MY RANGE ROVER RANGE ROVER SPORT
USA VOLUME AFFECTED	16,186
REPAIR	INSPECT/REPLACE DRIVER SEAT BELT ASSEMBLY
REPAIR TIME	c. 20 MINS
EXPECTED DATE FOR LAUNCH OF REPAIR PROCESS	Unexpected Launch Delay
CUSTOMER NOTIFICATION BY MAIL	JULY 1ST 2019 (INTERIM)

RECALL N336 - VEHICLE DOOR MAY NOT LATCH	
AFFECTED MODELS	16MY RANGE ROVER, RANGE ROVER SPORT
USA VOLUME AFFECTED	28,679
REPAIR	REPLACE BOTH LEFT HAND SIDE DOOR LATCHES
REPAIR TIME	BETWEEN 1.6 and 2.1 HOURS
EXPECTED DATE FOR LAUNCH OF REPAIR PROCESS	October 2nd 2019
CUSTOMER NOTIFICATION BY MAIL	JULY 19th 2019 (INTERIM)

