

SAFETY RECALL LAUNCH STATUS

N333, N336



RECALL N333 - DRIVER SEAT BELT EMERGENCY LOCKING RETRACTOR	
AFFECTED MODELS	16&17 MY RANGE ROVER RANGE ROVER SPORT
USA VOLUME CANADIAN VOLUME	16,186 1,455
REPAIR	INSPECT/REPLACE DRIVER SEAT BELT ASSEMBLY
REPAIR TIME	c. 20 MINS
EXPECTED DATE FOR LAUNCH OF REPAIR PROCESS	Launch delay
CUSTOMER NOTIFICATION BY MAIL	JUNE 27th 2019 (INTERIM)

RECALL N336 - VEHICLE DOOR MAY NOT LATCH	
AFFECTED MODELS	16MY RANGE ROVER, RANGE ROVER SPORT
USA VOLUME CANADIAN VOLUME	28,679 ZERO
REPAIR	REPLACE BOTH LEFT HAND SIDE DOOR LATCHES
REPAIR TIME	BETWEEN 1.6 and 2.1 HOURS
EXPECTED DATE FOR LAUNCH OF REPAIR PROCESS	EST. OCT 2nd 2019
CUSTOMER NOTIFICATION BY MAIL	JULY 19th 2019 (INTERIM)