

SAFETY RECALL LAUNCH STATUS

N336 – N335 VEHICLE DOOR MAY NOT LATCH



RECALL N336 - VEHICLE DOOR MAY NOT LATCH		ISSUES OBSERVED POST - N335	
AFFECTED MODELS	16MY RANGE ROVER, 16MY RANGE ROVER SPORT	AFFECTED MODELS	14-16MY RANGE ROVER SPORT 13-16MY RANGE ROVER
USA VOLUME AFFECTED	28,679	NAS VOLUME AFFECTED	65385 US
REPAIR	Keyless vehicle module software update and test operation of LH door latches	REPAIR	Door Latch
REPAIR TIME	Repair time for software is 0.2hrs and if req'd, between 0.8 and 1.6hrs for door latch replacement	REPAIR TIME	0.3hr – 2.2hrs Software/ Software +Latches
LAUNCHED	November 22nd 2019	LAUNCHED	JULY 2019
INTERIM CUSTOMER NOTIFICATION BY MAIL	JULY 19th 2019	Notes	Issues observed after completion of N335