


# SAFETY COMPLIANCE RECALL LAUNCH STATUS

## H256 –TIRE PLACARD LABEL INCORRECT



### RECALL H256 – INCORRECT TIRE LABEL

AFFECTED MODELS	19MY F-TYPE
VOLUME AFFECTED	241 USA and 4 CANADA
REPAIR	Replace Tire Placard on Driver's Lower B Post
REPAIR TIME	0.1 + 0.2 drive-in/out
EXPECTED DATE FOR RECALL LAUNCH	October 10 <sup>th</sup> 2019
CUSTOMER NOTIFICATION BY MAIL	On or before Nov 20 <sup>th</sup> , 2019



- The driver's B post tire compliance label is incorrect on certain vehicles with fitted 18" wheels.
- An incorrect rear tire size is stated on the label
- Replacement VIN specific labels should be ordered via Unipart using the JLRVINRQ special parts order form. Follow the parts instructions in the bulletins.
- Approx. 43 affected vehicles are in retailer inventory. Please use the inventory report in BBSS to identify affected unsold vehicles at your store.