

Toyota Motor North America, Inc.

Vehicle Safety & Compliance Liaison Office Mail Stop: W4-2D 6565 Headquarters Drive Plano, TX 75024

March 9, 2020

## AMENDED DEFECT INFORMATION REPORT (19V-741)

This supplements Toyota's Part 573 Report (19V-741) concerning the front passenger air bag assembly issue on certain Toyota and Lexus vehicles.

The subject recall affects certain Toyota and Lexus vehicles equipped with front passenger or driver air bag inflators as a "like-for-like" replacement under a prior recall which contain a non-desiccated, phase stabilized ammonium nitrate propellant. After the amended DIR filing on January 8, 2020, Toyota identified 17 additional vehicles that may have been equipped with the subject front passenger air bag assemblies. Thus, Toyota is supplementing its Part 573 Report (19V-741) of January 8, 2020 to add these vehicles to the affected population.

The total number of vehicles potentially involved (increase) are revised as noted below. The production period of each involved vehicle are not affected by this change.

Total Number of Vehicles Potentially Involved (revised):

| Toyota 4Runner        | : | 270     |
|-----------------------|---|---------|
| Toyota Corolla        | : | 521,426 |
| Toyota Corolla Matrix | : | 21      |
| Toyota RAV4           | : | 103     |
| Toyota Sequoia        | : | 137,491 |
| Toyota Sienna         | : | 61      |
| Toyota Tundra         | : | 234,646 |
| Toyota Yaris          | : | 162     |
| Toyota Scion xB       | : | 94      |
| Lexus ES350           | : | 207     |
| Lexus GX460           | : | 119     |
| Lexus IS250/350       | : | 141     |
| Lexus IS250C/350C     | : | 17      |
| Lexus IS-F            | : | 3       |
| Lexus SC430           | : | 33,459  |
| Total                 | : | 928,220 |
|                       |   |         |