

Toyota Motor North America, Inc.

Vehicle Safety & Compliance
Liaison Office
Mail Stop: W4-2D
6565 Headquarters Drive
Plano, TX 75024

June 1, 2020

AMENDED DEFECT INFORMATION REPORT (19V-741)

This supplements Toyota's Part 573 Report (19V-741) concerning the front passenger air bag assembly issue on certain Toyota and Lexus vehicles.

The subject recall affects certain Toyota and Lexus vehicles equipped with front passenger or driver air bag inflators as a "like-for-like" replacement under a prior recall which contain a non-desiccated, phase stabilized ammonium nitrate propellant. After the amended DIR filing on March 9, 2020, Toyota has developed effective methods to replace only the affected sub-components of the air bag assembly. Thus, Toyota is supplementing its Part 573 Report (19V-741) to include the option, where applicable, for replacement of only the front passenger airbag sub-assembly and inflator.

The Description of Corrective Repair Action is revised as noted below:

Description of Corrective Repair Action:

Depending on the vehicle model, dealers will replace the front driver inflator, front passenger airbag inflator, the airbag assembly, or the front passenger airbag sub-assembly and inflator.