

PRODUCT INVESTIGATION

RECALL ACTION – N412 20MY EVOQUE

CAPABLE OF GREAT THINGS
PALM SPRINGS 2020

SAFETY RECALL N412 EVOQUE HEADLINER	
AFFECTED MODELS	20MY EVOQUE
NAS VOLUME AFFECTED	3444 US 641 CAN of which 193 are in retailer stock
REPAIR	In temps below 25F, the adhesive bond attaching a metal plate to the headliner may reduce which can cause the plate to detach during an airbag deployment
REPAIR TIME	2 hrs
LAUNCH	Dec 5 th stop sale
Notes	Repair launch date TBC



Attach new fleece tape to bond metal plate to surface of headliner – both sides