

CAMPAIGN LAUNCH STATUS

N412 RECALL-20MY EVOQUE & N430 20MY EVOQUE AND DISCOVERY SPORT - EVAPORATIVE EMISSIONS PURGE VALVE



SAFETY RECALL N412 EVOQUE HEADLINER	
AFFECTED MODELS	20MY EVOQUE
NAS VOLUME AFFECTED	3444 US 637 CAN
REPAIR	In temps below 25F, the adhesive bond attaching a metal plate to the headliner may reduce which can cause the plate to detach during an airbag deployment
REPAIR TIME	2 hrs
LAUNCH	February 19 th 2020
Notes	2 nd customer mailing by 3/13/2020

SERVICE ACTION N430 20MY EVOQUE & DISCOVERY SPORT - EVAPORATIVE EMISSIONS	
AFFECTED MODELS	20MY EVOQUE and DISCOVERY SPORT 2.0L
VOLUME AFFECTED	20,658 USA 2682 CAN
REPAIR	Revised engine control module software is required to fix a purge valve calibration concern that could potentially increase evaporative emissions
REPAIR TIME	Est 0.2 hrs
LAUNCH	February 12 th 2020
Notes	

