

CAMPAIGN LAUNCH STATUS

FEBRUARY- MARCH SUMMARY



FSA/UPS Ref.:	Brand:	Title:	USA Volume:	Canada Volume	Ports	Retailer	Parts Required	Software Required	Market launch
CSP N430	Land Rover	20MY L551 L550 Evaporative Emissions Purge valve calibration	7761	853	Yes	Yes	No	Yes	2/4/2020
CSP N403	Land Rover	L405 L494 L462 L550 L560 Incorrect Warranty in Handbook (USA)	37526	0	Yes	Yes	Yes	No	2/10/2020
Recall N412	Land Rover	20MY L551 headliner plate retention	3444	637	Yes	Yes	Yes	No	2/18/2020
UPS H285	Jaguar	X761 - Quiescent Drain On Start Up Battery USA	2320	0	Yes	Yes	No	Yes	2/21/2020
UPS N440	Land Rover	L462 L550 L551 L560 - Quiescent Drain On Start Up Battery USA	3754	0	Yes	Yes	No	Yes	2/21/2020
Recall N422	Land Rover	20MY L462 Seat rail fixings missing. USA	34	0	Yes	Yes	Yes	No	2/21/2020
UPS H258	Jaguar	Inspect - hold or release F-TYPE Incorrect Routing of Brake Booster Vacuum Pipe CANADA	0	7	No	Yes	No	No	2/21/2020
Recall N390	Land Rover	14-16MY L494 ePAS rack motor mounting bolts CANADA	0	5647	No	Yes	Yes	No	2/27/2020
CSP H280	Jaguar	19-20MY I-PACE BeCM software update to address battery charge leakage and cell ageing.	1611	94	Yes	Yes	No	Yes	3/3/2020
UPS N445	Land Rover	L550 L551 20MY 9 Speed Automatic Transmission SW Update	6470	138	Yes	Yes	No	Yes	3/9/2020

PRINTED COPIES ARE UNCONTROLLED