

TOPIC	TYPE	RECALL CODE	QUESTION	ANSWER								
Safety Recall		34J6	What vehicles are included in Safety Recall 34J6?	<table border="1"> <thead> <tr> <th>Country</th> <th>Beginning Model Year</th> <th>Ending Model Year</th> <th>Vehicle</th> </tr> </thead> <tbody> <tr> <td>USA</td> <td>2013</td> <td>2015</td> <td>JETTA HYBRID</td> </tr> </tbody> </table>	Country	Beginning Model Year	Ending Model Year	Vehicle	USA	2013	2015	JETTA HYBRID
				Country	Beginning Model Year	Ending Model Year	Vehicle					
USA	2013	2015	JETTA HYBRID									
			What is the safety concern for Safety Recall 34J6?	Hairline cracks may develop in the accumulator housing of the transmission (mechatronic unit). The crack may lead to an internal leak, which, in turn, may lead to insufficient transmission oil pressure. If this happens, the transmission warning light will illuminate in the instrument panel. If the warning light is ignored and the vehicle is driven, the clutch may not engage. Failure of the clutch to engage may cause a sudden loss of power to the wheels, potentially leading to a vehicle crash.								
			What is the repair for Safety Recall 34J6?	Your authorized Volkswagen dealer will perform a TCM software update that will reduce the maximum pressure in the accumulator housing in order to reduce the stress level.								
			When will the repair for Safety Recall 34J6 be available?	This recall repair is not yet available, and is estimated to be available late 2020. Volkswagen will send you a letter via first-class mail to let you know when you can schedule the repair with your dealer.								
			Are there any precautions I should take because my vehicle is part of Safety Recall 34J6?	Customers are advised: Do not ignore the transmission warning light if it comes on. If the light comes on, owners are advised to contact an authorized Volkswagen dealer without delay to have the vehicle inspected. Please refer to the vehicle owner's manual for more information on warning lights.								