

March 11, 2020

Mr. Gerrit Hurenkamp Director of Engineering Arcimoto Inc 2034 W. 2nd Ave Eugene, OR 97402

Subject: Improper Traction-Power Harnesses

Dear Mr. Hurenkamp:

This letter serves to acknowledge Arcimoto Inc's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: ARCIMOTO/FUV/2019-2020

Mfr's Report Date: March 6, 2020

NHTSA Campaign Number: 20V-136

**Components:** ELECTRICAL SYSTEM:WIRING

Potential Number of Units Affected: 66

## **Problem Description:**

Arcimoto Inc. (Arcimoto) is recalling certain 2019-2020 FUV motorcycles. The traction-power harnesses large-gauge cable-lugs may be uncrimped or improperly crimped.

## **Consequence:**

Uncrimped or improperly crimped cable lugs can cause loss of drive power, increasing the risk of a crash. In addition, it can also cause localized high heat and arcing, increasing the risk of fire.

## **Remedy:**

Arcimoto will notify owners, and dealers will replace the traction-power harnesses, free of charge. The recall is expected to begin March 30, 2020. Owners may contact Arcimoto customer service at 1-541-683-6293.

## Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

NEF-150DM 20V-136

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components that need to be replaced to remedy this recall condition. This information should be provided in an amended 573 in the "Describe what distinguishes the remedy component from the recalled component" section.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be DeMara Magruder who may be reached by phone at (202) 366-8538, or by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff Chief, Recall Management Division Office of Defects Investigations Enforcement

