

August 10, 2020

Ms. Larissa Stoffels Exec Mgr, Vehicle Safety Daimler Trucks North America LLC 4747 N. Channel Ave Portland, OR 97217

Subject: Adjustable Brake Pedal Arm May Rotate

Dear Ms. Stoffels:

This letter serves to acknowledge Daimler Trucks North America LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: THOMAS BUILT BUSES/SAF-T-LINER C2/2021

Mfr's Report Date: July 28, 2020

NHTSA Campaign Number: 20V-435

**Components:** SERVICE BRAKES

Potential Number of Units Affected: 149

## **Problem Description:**

Daimler Trucks North America, LLC. (DTNA) is recalling certain 2021 Saf-T-Liner C2 School Buses. The adjustable brake pedal arm may rotate from its original location due to an incorrect fit between the pedal adjustment tube and the upper brake arm casting.

## **Consequence:**

A brake pedal that rotates out of position increases the risk of a crash.

## **Remedy:**

DTNA will notify owners, and dealers will install a new brake pedal assembly, free of charge. The recall is expected to begin September 25, 2020. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-857.

## Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150MR 20V-435

A description of how the products to be recalled differ from similar products that are not included in the recall (49 CFR 573.6 (c)(2)).

# AMENDED 573 REQUIRED.

A statement that the defect or noncompliance can cause a vehicle crash without prior warning; or a description of whatever prior warning may occur, and a statement that if this warning is not heeded, a vehicle crash can occur (49 CFR 577.5 (f)(1)). AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff Chief, Recall Management Division Office of Defects Investigations Enforcement

