

**Recall Quarterly Report****20V-103**

**Manufacturer Name :** Terex South Dakota, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 20V-103 /SN681  
**Recall Subject :** Limit Switch Improperly Installed  
**Owner Notification Beginning Date :** APR 14, 2020  
**Owner Notification End Date:** JUN 26, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
7	JAN 26, 2022	2021-4	523	251	0	0
6	OCT 12, 2021	2021-3	523	239	0	0
5	JUL 22, 2021	2021-2	523	224	0	0
4	APR 23, 2021	2021-1	523	222	0	0
3	JAN 06, 2021	2020-4	523	174	0	0
2	OCT 08, 2020	2020-3	523	89	0	0
1	JUL 22, 2020	2020-2	523	32	0	0

This Document Last Updated : JAN 27, 2022

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.