OMB Control No.: 2127-0004

Part 573 Safety Recall Report

Manufacturer Name :Freedman Seating CompanySubmission Date :JUN 19, 2020NHTSA Recall No. :20E-004Manufacturer Recall No. :NR

Manufacturer Information :

Manufacturer Name : Freedman Seating Company Address : 4545 West Augusta BLVD Chicago IL 60651

Company phone : 8004434540

Equipment Information :

Brand / Trade 1:	Freedman
Model :	2pl GO-ES 3pt Foldaway Seat Assy
Part No. :	43705
Size :	36" width
Function :	seating
Descriptive Information :	The recall population was determined by identifying the total number of GO-ES Foldaway Seats manufactured from When Freedman received the suspect retractor through the production date after supplier notification. These seat belts in these seats can be easily inspected for non-conformance and replaced if necessary.
Production Dates :	AUG 20, 2019 - JAN 23, 2020
Brand / Trade 2:	Freedman
Model :	2pl GO-ES 3pt Foldaway Seat Assy
Part No. :	45467
Size :	36" width
Function :	seating
Descriptive Information :	The recall population was determined by identifying the total number of GO-ES Foldaway Seats manufactured from When Freedman received the suspect retractor through the production date after supplier notification. These seat belts in these seats can be easily inspected for non-conformance and replaced if necessary.
Production Dates :	AUG 20, 2019 - JAN 23, 2020

Population :

Number of potentially involved : 2,500 Estimated percentage with defect : $10\ \%$

云 🔨 🗛 🖈

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

20E-004

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Brand / Trade 3:	Freedman
	2pl 3pt Foldaway Seat Assy
Part No. :	
	36" width
Function :	seating
Descriptive Information :	The recall population was determined by identifying the total number of 3pt Foldaway Seats manufactured from when Freedman received the suspect retractor through the production date after supplier notification. These seat belts in these seats can be easily inspected for non-conformance and replaced if necessary.
Production Dates :	SEP 19, 2019 - JAN 23, 2020
Brand / Trade 4 :	Freedman
Model :	2pl 3pt Foldaway Seat Assy
Part No. :	26401
Size :	36" width
Function :	seating
Descriptive Information :	The recall population was determined by identifying the total number of 3pt Foldaway Seats manufactured from when Freedman received the suspect retractor through the production date after supplier notification. These seat belts in these seats can be easily inspected for non-conformance and replaced if necessary.
	nocobbarji

Page 3

Description of Noncompliance :

The retractor incorporated in the subject seats is designed to be installed into applications where the seat back can fold down, such that the retractor moves with it. This design requires the retractor to have a block out mechanism. Without the block out mechanism, the vehicle sense mechanism in the retractor would lock when the retractor is tilted as the seat is folded down. Since it also will pay in webbing as the belt length is shortened due to the folding, the seat would not be able to be brought back upright because the shortened belt would be locked.
The block out mechanism prevents this locking issue by blocking out the vehicle sense locking mechanism based on how much webbing is on the spool and how much webbing has been paid out. It unblocks the vehicle sensor and resumes normal operation when a pre-set amount of webbing is extracted. The amount of webbing required to be extracted to enable normal operation of the retractor is referred to as the "block out zone."
In the suspect lots of retractors, the block out zone may have not been set correctly. If this occurred, it could block the vehicle sensor and affect the proper operation of the seat belt.
209 - Seat belt assemblies
NR
The potential for the vehicle sense to not engage represent a non-compliance to FMVSS209.
A part internal to the retractor which controls the timing of this block out feature was potentially installed incorrectly.
The defect can be easily identified by inspection, but a user under normal course of wearing the belt would not detect it.

Involved Components :

Component Name :	NR
Component Description :	NR
Component Part Number :	NR

Supplier Identification :

Component Manufacturer

Name : Joyson Safety Systems

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Address : 2500 Innovation Drive Auburn Hills MICHIGAN 48326 Country : United States

Chronology:

Freedman Seating Corp purchases retractor components for installation into foldable seating systems.

On January 6, 2020, a mis-built part was discovered during Lot Acceptance Testing at the supplier.

On 1/9/2020 this issue was first reported to Freedman as matter under investigation.

Subsequent investigation identified the deficiency described above and confirmed the parts in the field were at risk of exhibiting this defect.

On 1/29/20, this information was reviewed with the supplier and the determination was made that a potential defect existed.

Description of Remedy :

Description of Remedy Program :	Freedman will notify those vehicle builders who purchased the seat and Freedman will provide a Seat Inspection & Repair Procedure. Freedman/ JSS will reimburse the cost of repairs relating to this recall, including both parts and labor, at no cost to the vehicle manufacturer or vehicle owner. Parts for this recall are anticipated to be available for shipment. Vehicle owners may contact Freedman Customer Service at 800-443-4540
How Remedy Component Differs from Recalled Component :	The internal mechanisms in the retractor will be properly assembled.
	On January 8, 2020, the seat belt supplier implemented 100% block out testing. On January 23, 2020, the seat manufacturer implemented retractor inspection during seat assembly.

Recall Schedule :

Description of Recall Schedule :	Customer recall notification letters started mailing 4/6/2020.
Planned Dealer Notification Date :	APR 06, 2020 - APR 10, 2020
Planned Owner Notification Date :	APR 06, 2020 - APR 10, 2020

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR Address : NR NR Country : NR Company Phone : NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573