

# Part 573 Safety Recall Report

# 20V-170

**Manufacturer Name :** KTM North America, Inc.

**Submission Date :** MAR 19, 2020

**NHTSA Recall No. :** 20V-170

**Manufacturer Recall No. :** HTB2011



## Manufacturer Information :

**Manufacturer Name :** KTM North America, Inc.

**Address :** 1119 Milan Avenue

Amherst OH 44001

**Company phone :** 440-985-3553

## Population :

**Number of potentially involved :** 1,500

**Estimated percentage with defect :** 10 %

## Vehicle Information :

**Vehicle 1 :** 2019-2020 Husqvarna Motorcycles 701 Svartpilen

**Vehicle Type :** MOTORCYCLES

**Body Style :** OTHER

**Power Train :** GAS

**Descriptive Information :** The component was used on Husqvarna 701 Vitpilen for the model year 2018, 2019 and a portion of 2020; 701 Svartpilen model year 2019 and portion of 2020.

Dealers must immediately stop selling affected 701 Svartpilen and Vitpilen motorcycles listed above. Vehicles will be locked out from retail registration in Dealer.net until the remedy is in place.

The total US units of 701 Vitpilen's is 812; the total number of 701 Svartpilen's is 688. The total population for both models is 1500.

**Production Dates :** JAN 17, 2018 - JAN 31, 2020

**VIN Range 1 : Begin :** VBKUPV404JM715540 **End :** VBKUPV400LM773843  Not sequential

**Vehicle 2 :** 2018-2020 Husqvarna Motorcycle 701 Vitpilen

**Vehicle Type :** MOTORCYCLES

**Body Style :** OTHER

**Power Train :** GAS

**Descriptive Information :** The component was used on Husqvarna 701 Vitpilen for the model year 2018, 2019 and a portion of 2020; 701 Svartpilen model year 2019 and portion of 2020.

Dealers must immediately stop selling affected 701 Svartpilen and Vitpilen motorcycles listed above. Vehicles will be locked out from retail registration until the remedy is in place.

The total US units of 701 Vitpilen's is 812; the total number of 701 Svartpilen's is 688. The total population for both models is 1500.

**Production Dates :** JAN 17, 2018 - JAN 31, 2020

VIN Range 1 : Begin : VBKUPV404JM715540 End : VBKUPV400LM773843  Not sequential

**Description of Defect :**

Description of the Defect : Husqvarna Motorcycles North America, Inc. has decided that a defect which relates to motor vehicle safety exists with the motorcycle models and years listed above in which the fuel may seep or leak from the fuel level sensor and fuel pump mounting area.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : During operation or while sitting still, this occurrence may increase the risk of injury and/or damage to the rider and/or property.

Description of the Cause : Investigation is ongoing

Identification of Any Warning that can Occur : During operation or while sitting still, this occurrence may increase the risk of injury and/or damage to the rider and/or property. The rider may observe and smell fuel on or near the tank.

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

Investigation is ongoing. Dealers must immediately stop selling affected 701 Svartpilen and Vitplen motorcycles listed above. Vehicles will be locked out from retail registration until the remedy is in place.

**Description of Remedy :**

Description of Remedy Program : TBD

How Remedy Component Differs from Recalled Component : TBD

Identify How/When Recall Condition was Corrected in Production : TBD

**Recall Schedule :**

Description of Recall Schedule : Interim Notification to Dealers and Customers.

Planned Dealer Notification Date : MAR 23, 2020 - SEP 14, 2020

Planned Owner Notification Date : MAY 15, 2020 - SEP 10, 2021

\* NR - Not Reported