OMB Control No.: 2127-0004

Part 573 Safety Recall Report

20V-194

Manufacturer Name: Keystone RV Company

NHTSA Recall No.: 20V-194

Manufacturer Recall No.: 20-376



Manufacturer Information:

Manufacturer Name: Keystone RV Company

Address: PO Box 2000

2642 Hackberry Drive Goshen IN

46527

Company phone: 574-535-2100

Population:

Number of potentially involved: 94 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2018-2020 Crossroads Hampton 371FKL

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Model 371FKL

Production Dates: AUG 21, 2017 - OCT 30, 2019

 VIN Range 1 : Begin :
 4YDT37123K5330053
 End :
 4YDT37120K5330169
 ✓ Not sequential

 VIN Range 2 : Begin :
 4YDT37124L5330029
 End :
 4YDT37129L5330110
 ✓ Not sequential

 VIN Range 3 : Begin :
 4YDT3712XJ5330002
 End :
 4YDT37129J5330041
 ✓ Not sequential

Description of Defect:

Description of the Defect: It has been decided that the vehicles fail to conform to the requirements of Part

567, "Certification." The vehicles subject to this recall may have been

manufactured with the incorrect information on the Federal Identification Tag. The tag indicates the tire pressure as 6 PSI. The correct tire pressure is 80 PSI.

FMVSS 1: 567 - Certification

FMVSS 2: NR

Description of the Safety Risk: Fails to conform to the requirements of Part 567, "Certification." An incorrect

label may lead to unintentionally underinflating the tires, increasing the risk

of a crash.

Description of the Cause: The incorrect tire pressure information was printed on the label.

Identification of Any Warning PSI on the Federal Identification Tag does not match information for the rim

that can Occur: and tire.

Involved Components:

Component Name 1 : NR
Component Description : NR
Component Part Number : NR

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

NR

Country: NR

Chronology:

4/1/2020 - Report was made by engineering that the FED ID tag info was incorrect for the tire PSI.

4/1/2020 - Range and Scope completed.

Description of Remedy:

Description of Remedy Program: The remedy is to replace the Federal Identification Tag.

How Remedy Component Differs The repair will conform to requirements of Part 567, "Certification."

from Recalled Component:

Identify How/When Recall Condition There are none of these units currently in possession of the Original

was Corrected in Production: Equipment Manufacturer. All future production will have the corrected

Federal Identification Tag.

Recall Schedule:

Description of Recall Schedule: Keystone will notify the dealers and owners of the recreational vehicles

by letter. A final copy of the owner letter will be provided to NHTSA,

along with the dealer repair procedures.

Planned Dealer Notification Date: JUN 01, 2020 - JUN 01, 2020 Planned Owner Notification Date: JUN 01, 2020 - JUN 01, 2020

Part 573 Safety Recall Report	20V-194	Page 3
* NR - Not Reported		
The information contained in this report was submitted	d pursuant to 49 CFR §573	