Part 573 Safety Recall Report

Manufacturer Name :Daimler Trucks North America LLCSubmission Date :MAY 05, 2020NHTSA Recall No. :20V-252Manufacturer Recall No. :FL-849



Manufacturer Name :Daimler Trucks North America LLCAddress :4747 N. Channel AvenuePortland OR 97217-3849800-745-8000

Vehicle Information :

Vehicle 1:	2010-2020 Tho	mas Built Buses	Saf-T-Liner	HDX	
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES				
Body Style :					
Power Train :	NR				
Descriptive Information :	On the affected Saf-T-Liner HDX School Buses with a specific rear emergency exit window.				
Production Dates :	APR 20, 2009 -	DEC 10, 2018			
VIN Range 1:	Begin :	NR	End: NR		Not sequential


Population :

Description of Noncompliance :

-	On the affected school buses, letters on the instruction label for the rear emergency exit window measure less than the required 1cm. As per the requirements of FMVSS 217 5.5.3(b), these instructions shall be in letters at least 1 centimeter high.
FMVSS 1 :	217 - Bus emergency exits and window retention and release
FMVSS 2 :	NR
Description of the Safety Risk :	A non-compliance with FMVSS 217 Bus emergency exits and window retention and release may delay the reaction time for certain people to open the exit.
Description of the Cause :	NR
Identification of Any Warning that can Occur :	NR

Involved Components :

The information contained in this report was submitted pursuant to 49 CFR §573





Number of potentially involved : 7,979

Estimated percentage with defect : 100 %

Part 573 Safety Recall Report

20V-252

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology :

End of March 2020, DTNA received a notification from NHTSA about a potential non-compliant emergency exit window label. Beginning of April 2020, TBB opened an investigation to determine the root cause and identify potential field exposure. End of April 2020, DTNA completed a review of warranty and field reports, and no reports or complaints were identified, however, DTNA was able to confirm there was a population of vehicles that may contain the issue. April 30, 2020, DTNA decided to conduct a voluntary non-compliance recall on certain school buses built with incorrect emergency exit window labels.

Description of Remedy :

Description of Remedy Program :	Customers will be mailed a new label to attach to the exit window. Copies of the reimbursement plan will be submitted as a supplemental report when available. Customer notification will be done by first class mail using Daimler Trucks North America records to determine the customers affected.
How Remedy Component Differs from Recalled Component :	NR
Identify How/When Recall Condition was Corrected in Production :	NR

Recall Schedule :

Description of Recall Schedule :	Customer notification will be made by first class mail using Daimler
	Trucks North America records to determine the customers affected.
Planned Dealer Notification Date :	JUL 03, 2020 - JUL 03, 2020

Part 573 Safety Recall Report

20V-252

Planned Owner Notification Date : JUL 03, 2020 - JUL 03, 2020

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573