

Part 573 Safety Recall Report

20V-468

Manufacturer Name : Jayco, Inc.

Submission Date : AUG 10, 2020

NHTSA Recall No. : 20V-468

Manufacturer Recall No. : same as 20V-xxx



Manufacturer Information :

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

Population :

Number of potentially involved : 545

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2020-2021 Class C Motorhome Melbourne, Melbourne Prestige, Qwest

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : MB Sprinter - provided list of recalled chassis VINS - Jayco matched to Jayco production reports to call out Jayco products affected

Production Dates : JAN 13, 2020 - AUG 17, 2020

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : The electric cables in the seat wiring harness could become jammed and damaged in the swivel-seat frame. (MB RECALL 20V322)

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If electric cables in the wiring harness become jammed and damaged in the swivel seat frame, the operation of the side airbag within the seat could be adversely affected which could cause the side airbag to deploy inadvertently or not deploy as designed in the event of a crash, increasing the risk of injury to vehicle occupants.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

8-4-2020 Jayco received Recall notification letter regarding Sprinter chassis (recall 20V-322) - Chassis VINS provided were matched to the Jayco motorhomes Serial numbers - Safety Committee agreed that a pass through recall is required -

Description of Remedy :

Description of Remedy Program : An authorized MB sprinter dealer will Inspection of the seat wiring harness (left/ rift) of the front seats and will add clips or cable ties as required to ensure that the course routing is according to specification. .

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Jayco will post recall information and mail notification letter to Jayco dealers with affected inventory, when MB has parts available to their Service Centers.

Planned Dealer Notification Date : AUG 28, 2020 - AUG 28, 2020

Planned Owner Notification Date : NR - NR

* NR - Not Reported