

Part 573 Safety Recall Report

20V-518

Manufacturer Name : Kia Motors America**Submission Date :** AUG 27, 2020**NHTSA Recall No. :** 20V-518**Manufacturer Recall No. :** SC196**Manufacturer Information :**

Manufacturer Name : Kia Motors America

Address : 111 Peters Canyon Road
Irvine CA 92606

Company phone : 800-333-4542

Population :

Number of potentially involved : 9,443

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2019-2019 Kia Stinger

Vehicle Type : LIGHT VEHICLES

Body Style : ALL

Power Train : GAS

Descriptive Information : Certain 2019 model year Kia Stinger vehicles equipped with 3.3L T-GDI engines manufactured from June 21, 2018 through July 9, 2019.

The recall population was determined by a review of vehicle production records. The vehicles subject to this recall were not produced in VIN order. Customers seeking information about their specific vehicle will be referred to Kia's Consumer Assistance Center or their Kia dealer.

Production Dates : JUN 21, 2018 - JUL 09, 2019

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : An engine compartment fire may occur while driving in the area where the Hydraulic Electronic Control Unit (HECU) is located. The cause of fire is currently unknown.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Fire increases the risk of injury.**Description of the Cause :** Unknown. Kia is still investigating possible causes of this condition.

Identification of Any Warning that can Occur : Illumination of various warning lights on instrument panel including tire pressure warning light, ABS warning light, MIL warning light, burning/melting odor, smoke from engine compartment.

Involved Components :

Component Name 1 : TBD

Component Description : TBD

Component Part Number : TBD

Supplier Identification :**Component Manufacturer**

Name : TBD

Address : NR

NR

Country : NR

Chronology :

See attached document titled "2019MY Stinger Engine Compartment Fire Chronology"

Description of Remedy :

Description of Remedy Program : TBD

How Remedy Component Differs from Recalled Component : TBD

Identify How/When Recall Condition was Corrected in Production : TBD. However, there have been no similar fire incidents with the 2020MY Stinger.

Recall Schedule :

Description of Recall Schedule : Notice will be sent to the dealers on October 20, 2020, and to the vehicle owners on October 26, 2020.

Planned Dealer Notification Date : OCT 20, 2020 - OCT 20, 2020

Planned Owner Notification Date : OCT 26, 2020 - OCT 26, 2020

* NR - Not Reported