

Part 573 Safety Recall Report

20V-566

Manufacturer Name : Newmar Corporation**Submission Date :** SEP 18, 2020**NHTSA Recall No. :** 20V-566**Manufacturer Recall No. :** 20V-529**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 350

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2021-2021 Newmar Canyon Star

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the tire valve stem extension for the inner wheel may contact the outer wheel rim opening and become damaged. Extensive damage to the valve stem extension may result in a loss of tire pressure of the inner wheel, extended driving with an overloaded tire may increase the risk of a crash. Repairs will be performed by Daimler Trucks North America authorized service facilities at no cost to the customer.

2021 Canyon Star= 23 units

Production Dates : MAY 24, 2020 - SEP 08, 2020

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2018-2019 Newmar Ventana

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the tire valve stem extension for the inner wheel may contact the outer wheel rim opening and become damaged. Extensive damage to the valve stem extension may result in a loss of tire pressure of the inner wheel, extended driving with an overloaded tire may increase the risk of a crash. Repairs will be performed by Daimler Trucks North America authorized service facilities at no cost to the customer.

2018 Ventana =321 units

2019 Ventana= 6 units

Production Dates : MAY 24, 2020 - SEP 08, 2020

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes, the tire valve stem extension for the inner wheel may contact the outer wheel rim opening and become damaged. Extensive damage to the valve stem extension may result in a loss of tire pressure of the inner wheel, extended driving with an overloaded tire may increase the risk of a crash.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : On certain motorhomes, the tire valve stem extension for the inner wheel may contact the outer wheel rim opening and become damaged. Extensive damage to the valve stem extension may result in a loss of tire pressure of the inner wheel, extended driving with an overloaded tire may increase the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :**Component Manufacturer**

Name : Daimler Trucks North America LLC

Address : P.O. Box 4090
Portland OREGON 97208

Country : United States

Chronology :

On 09/10/2020, DTNA notified Newmar of a potential safety defect on Newmar motorhomes. On 09/14/2020, a decision was made to start a recall for FL-861///20V-529. Today, 09/18/2020, Newmar is giving notice to

NHTSA for a recall.

Description of Remedy :

Description of Remedy Program : Daimler Trucks North America will be conducting this recall in its entirety. At this time, a remedy is not available. DTNA will contact authorized service facilities when a remedy is available.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : On or before 11/17/2020, customer/dealers will be mailed out.

Planned Dealer Notification Date : NOV 17, 2020 - NOV 17, 2020

Planned Owner Notification Date : NOV 17, 2020 - NOV 17, 2020

* NR - Not Reported