

Part 573 Safety Recall Report

20V-612

Manufacturer Name : Suzuki Motor of America, Inc.

Submission Date : OCT 09, 2020

NHTSA Recall No. : 20V-612

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Suzuki Motor of America, Inc.

Address : 3251 East Imperial Highway

Brea CA 92821-6795

Company phone : 714-996-7040

Population :

Number of potentially involved : 2,040

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2018 Suzuki GSX250R

Vehicle Type : MOTORCYCLES

Body Style : ALL

Power Train : GAS

Descriptive Information : The recall population is based on production records. Vehicles not included in the recall population were equipped with a redesigned headlamp assembly that included a revised headlamp bulb attachment system.

Production Dates : MAR 25, 2017 - MAY 25, 2017

VIN Range 1 : Begin : LC6DN11A0J1100008 **End :** LC6DN11A2J1102374

Not sequential

Description of Defect :

Description of the Defect : The low and/or high beam headlamp bulb filament may break prematurely.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Sudden loss of headlamp illumination could reduce operator visibility and/or conspicuity, increasing the risk of a crash.

Description of the Cause : Suzuki has not yet determined the root cause of this condition.

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : Headlamp Assembly

Component Description : Vehicle headlamp

Component Part Number : 35100-20K30

Supplier Identification :

Component Manufacturer

Name : Chongqing JiaLi jianqiao lamps Co.,LT

Address : 11#, Chuangye Road

ShuangFu Street Jiangjin District, ChongQing FOREIGN STATES

Country : China

Chronology :

The chronology of principal events is attached as a separate document.

Description of Remedy :

Description of Remedy Program : Suzuki has not yet determined a remedy. Suzuki will notify NHTSA through an amended Part 573 report when a remedy has been determined.

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : Initial notification to dealers was transmitted 10/1/2020.
Interim customer notification letters were mailed 10/9/2020.

Remedy date: TBD

Planned Dealer Notification Date : OCT 01, 2020 - OCT 01, 2020

Planned Owner Notification Date : OCT 09, 2020 - OCT 09, 2020

* NR - Not Reported