

Part 573 Safety Recall Report

20V-694

Manufacturer Name : Jaguar Land Rover North America, LLC

Submission Date : JUN 21, 2021

NHTSA Recall No. : 20V-694

Manufacturer Recall No. : N400



Manufacturer Information :

Population :

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 11,084

Address : 100 Jaguar Land Rover Way

Estimated percentage with defect : 100 %

Mahwah NJ 07495

Company phone : 8188500

Vehicle Information :

Vehicle 1 : 2019-2020 LAND ROVER DISCOVERY

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : NR

Descriptive Information : A concern has been identified with certain 2019 and 2020 Model Year Discovery vehicles, built at the Nitra assembly plant, where due to insufficient contact of the battery ground stud to the chassis, the vehicle may exhibit various electrical faults. The vehicle could cut out while in motion and may lose all electrical power. 11,084 Discovery vehicles in the United States and Federalized Territories. The basis of the recall population was derived from Jaguar Land Rover data where the VIN range for vehicles affected were determined by specific model type and specification 2019 and 2020MY Discovery vehicles built from September 21, 2018 to August 31, 2020.

Production Dates : SEP 21, 2018 - AUG 31, 2020

VIN Range 1 : Begin : SALRR2RV6K2400085 End : SALRG2RV9K2414715

☐ Not sequential

VIN Range 2 : Begin : SALRT2RV6L2414734 End : SALRR2RV1L2443301

☐ Not sequential

Description of Defect :

Description of the Defect : A concern has been identified with certain 2019 and 2020 Model Year Discovery vehicles, built at the Nitra assembly plant, where due to insufficient contact of the battery ground stud to the chassis, the vehicle may exhibit various electrical faults. The vehicle could cut out while in motion and may lose all electrical power.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Vehicle cut out while in motion and loss of exterior lighting without warning to the driver could lead to an increased risk of an accident.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name 1 : Earth Stud

Component Description : Ground Stud

Component Part Number : W780285

Supplier Identification :

Component Manufacturer

Name : Jaguar Land Rover Limited

Address : Abbey Road

Whitley, Coventry Foreign States CV3 4LF

Country : United Kingdom

Chronology :

See file "Recall N400 Chronology".

Description of Remedy :

Description of Remedy Program : Retailers will replace the ground stud with a modified part. There will be no charge to owners for this repair. The vehicles will be covered under Jaguar Land Rover's new vehicle warranty program. Customers who have paid for a repair of this defect will be reimbursed by the Jaguar Land Rover reimbursement plan, subject to terms and conditions.

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : Distribution of owner notification letters will occur on or before January 8, 2021. Notifications to retailers will occur on November 24, 2020.

Planned Dealer Notification Date : NOV 24, 2020 - NOV 24, 2020

Planned Owner Notification Date : JAN 08, 2021 - JAN 08, 2021

* NR - Not Reported