OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 20V-697

**Manufacturer Name:** Lion Electric Company

**Submission Date:** NOV 12, 2020 **NHTSA Recall No.:** 20V-697

**Manufacturer Recall No.:** NR



#### **Manufacturer Information:**

Manufacturer Name: Lion Electric Company

Address: 921, chemin de la Riviere-du-Nord

Saint-Jerome, Quebec, Canada 00 J7Y

5G2

Company phone: 1-855-546-6706

# **Population:**

Number of potentially involved : 8 Estimated percentage with defect : 100 %

#### **Vehicle Information:**

Vehicle 1: 2016-2019 Lion LionC/Lion360

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER

Power Train: HYBRID ELECTRIC

Descriptive Information: All vehicles produced with wheelchair lift are affected. We have 8 vehicles with this

configuration. LionC and Lion360 2016,2017 and 2019

Production Dates: AUG 15, 2016 - MAY 20, 2019

 VIN Range 1 : Begin :
 2A9SP2226GJ198276
 End :
 2A9SP2228GJ198277
 □ Not sequential

 VIN Range 2 : Begin :
 2A9SP2226GJ198276
 End :
 2A9SP2228GJ198277
 □ Not sequential

 VIN Range 3 : Begin :
 2A9CP2226KJ198341
 End :
 2A9CP2223KJ198345
 □ Not sequential

 VIN Range 4 : Begin :
 2A9SP2226GJ198276
 End :
 2A9CP2223KJ198277
 □ Not sequential

 VIN Range 5 : Begin :
 2A9CP2226KJ198341
 End :
 2A9SP2228GJ198277
 □ Not sequential

 VIN Range 7 : Begin :
 2A9CP2226KJ198341
 End :
 2A9CP2223KJ198345
 □ Not sequential

 VIN Range 7 : Begin :
 2A9CP2226KJ198341
 End :
 2A9CP2223KJ198345
 □ Not sequential

# **Description of Noncompliance:**

Description of the As a result of our certification tests on shoulder belt anchors and ground Noncompliance : anchors, the anchors do not withstand the minimum required force, not

meeting FMVSS 222 section S5.4.1.3.

FMVSS 1: 222 - School bus passenger seating and crash protection

FMVSS 2: NR

Description of the Safety Risk: In the event of an impact, the belt anchorage and ground attachment points

could become detached, compromising passenger safety. This defect

therefore represents a human safety issue. To date, no warranty claims and

no cases have been reported to the service department.

Description of the Cause: NR

Identification of Any Warning NR that can Occur :

## **Involved Components:**

Component Name 1: NR
Component Description: NR
Component Part Number: NR

# **Supplier Identification:**

### **Component Manufacturer**

Name: NR Address: NR NR

Country: NR

## **Chronology:**

After updating our tests, we found that they did not comply with the standards.

#### **Description of Remedy:**

Description of Remedy Program : Based on the success of our tests we have modified our assembly

procedures. All vehicles delivered now comply with the standard. We will contact customers affected by this recall and schedule appointments to

make the necessary modifications.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

### **Recall Schedule:**

Description of Recall Schedule: NR

The information contained in this report was submitted pursuant to 49 CFR §573

# **Part 573 Safety Recall Report**

20V-697

Page 3

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: NOV 16, 2020 - NOV 30, 2020

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573