

Part 573 Safety Recall Report

20V-703

Manufacturer Name : Winnebago Industries, Inc.

Submission Date : MAR 24, 2021

NHTSA Recall No. : 20V-703

Manufacturer Recall No. : 20V703



Manufacturer Information :

Population :

Manufacturer Name : Winnebago Industries, Inc.

Number of potentially involved : 242

Address : PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436

Estimated percentage with defect : 100 %

Company phone : 1-641-585-3535

Vehicle Information :

Vehicle 1 : 2021-2021 Winnebago Revel, Vista, Sunstar, Adventurer

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Recall 20E-074 and use of our production records showing models and VINs.

Production Dates : AUG 19, 2020 - SEP 21, 2020

VIN Range 1 : Begin : NR End : NR

Not sequential

Description of Defect :

Description of the Defect : Reference 20E-074. The recall relates to LLCI P2K Bed Systems. There is the possibility of a gear in the motor experiencing an issue which could allow the bed to extend prior to the safety strap engaging.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If safety straps are not used, the bed could drop down resulting in death, personal injury, and/or property damage

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : LCI P2K Bedlift (motor)

Component Description : Power Bed

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Lippert

Address : 1902 West Sample Street
South Bend Indiana 46619

Country : United States

Chronology :

9-28-20 E-mail from Lippert to Winnebago Supplier Quality Assurance

9-29-20 Rework campaign HOLD NOTICE 847

10- -20 Lippert and QAI performed lot and WH campaign on 254 bed asm in house

11-9-20 Lippert sent e-mail (recall notice 20E-074) to Dean Casad Dir of Customer Exper

11-13-19 Submitted 573 notice on NHTSA portal. (for the 242 built units)

Description of Remedy :

Description of Remedy Program : submit a claim to documenting the completed repair for payment of the labor charges. LCI's Customer Service department may be reached at 574-538-4514 or via email at recall@lci1.com if there are any questions. LCI does not require advance contact or a pre-auth be obtained; labor allowance for this repair is 0.8 and the original motor is required to be returned. LCI will coordinate shipments of the needed replacement motor with you.

How Remedy Component Differs from Recalled Component : The motor will have Black and Red wires the replaced motor will have Black and Green wires

Identify How/When Recall Condition was Corrected in Production : LCI came inhouse and did a motor replacement

Recall Schedule :

Description of Recall Schedule : dates are shown to the right

Planned Dealer Notification Date : DEC 18, 2020 - DEC 18, 2020

Planned Owner Notification Date : JAN 04, 2021 - JAN 04, 2021

* NR - Not Reported