

Part 573 Safety Recall Report

20V-703

Manufacturer Name : Winnebago Industries, Inc

Submission Date : NOV 13, 2020

NHTSA Recall No. : 20V-703

Manufacturer Recall No. : 164



Manufacturer Information :

Manufacturer Name : Winnebago Industries, Inc

Address : PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436

Company phone : 1-641-585-3535

Population :

Number of potentially involved : 242

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2021-2021 Winnebago Revel, Vista, Adventurer

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Recall 20E-074 and use of our production records showing models and VINs.

Production Dates : AUG 19, 2020 - SEP 21, 2020

VIN Range 1 : Begin : NR **End :** NR Not sequential

Description of Defect :

Description of the Defect : Reference 20E-074. The recall relates to LLCI P2K Bed Systems. There is the possibility of a gear in the motor experiencing an issue which could allow the bed to extend prior to the safety strap engaging.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If safety straps are not used, the bed could drop down resulting in death, personal injury, and/or property damage

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : LCI P2K Bedlift (motor)

Component Description : Power Bed

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Lippert

Address : 1902 West Sample Street
South Bend INDIANA 46619

Country : United States

Chronology :

9-28-20 E-mail from Lippert to Winnebago Supplier Quality Assurance

9-29-20 Rework campaign HOLD NOTICE 847

10- -20 Lippert and QAI performed lot and WH campaign on 254 bed asm in house

11-9-20 Lippert sent e-mail (recall notice 20E-074) to Dean Casad Dir of Customer Exper

11-13-19 Submitted 573 notice on NHTSA portal. (for the 242 built units)

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : The motor will have Black and Red wires the replaced motor will have Black and Green wires

Identify How/When Recall Condition was Corrected in Production : LCI came inhouse and did a motor replacement

Recall Schedule :

Description of Recall Schedule : TBD

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported