OMB Control No.: 2127-0004

8

Part 573 Safety Recall Report

Manufacturer Name :Chrysler (FCA US LLC)Submission Date :NOV 18, 2020NHTSA Recall No. :20V-714Manufacturer Recall No. :W86

Manufacturer Information :

Manufacturer Name : Chrysler (FCA US LLC) Address : 800 Chrysler Drive CIMS 482-00-91 Auburn Hills MI 48326-2757 Company phone : 1-800-853-1403

Vehicle Information :

	020-2020 Alfa Romeo Giulia	
Vehicle Type :	DOOD	
Body Style: 4 Power Train: N		
-	ome 2020 MY Alfa Romeo Giulia vehicles may have been built with rear brake discs nat may fracture.	
w ir lo	he suspect population period for vehicles in this recall began February 17, 2020, when rear brake discs with a new finish and new material mixing machine were atroduced into production, through July 27, 2020, when the suspect parts were no onger used in production of vehicles included in this recall. Supplier and plant roduction records were used to identify the suspect period.	
	imilar vehicles not included in the recall were manufactured outside of the suspect eriod or built with rear brake discs that utilize a different process.	
Production Dates : FEB 17, 2020 - JUL 27, 2020		
VIN Range 1: Be	gin: NR End: NR 🗌 Not sequential	
Description of Defect :		
Description of the Defect	: The suspect rear brake discs may fracture during vehicle operation.	
FMVSS 1		
FMVSS 2	: NR	
Description of the Safety Risk	A rear brake disc fracture during vehicle operation may result in a dimunition of braking performance, which can cause a vehicle crash without prior warning.	
Description of the Cause	: NR	



Number of potentially involved :

Estimated percentage with defect : 100 %

Population :

20V-714

Part 573 Safety Recall Report

Identification of Any Warning None that can Occur :

Involved Components :

Component Name 1: Brake kit

Component Description : Set of brake discs and pads

Component Part Number: 68416484AA

Supplier Identification :

Component Manufacturer

Name : Brembo Spa Address : Brembo 25 Curno FOREIGN STATES N/A Country : Italy

Chronology :

• On October 27, 2020, the brake disc supplier, Brembo, informed the FCA Italy Quality department of a potential issue involving brake discs with fractures.

- On October 27, 2020, FCA Italy Quality began to sort brake discs at the Cassino assembly plant.
- On October 28, 2020, FCA Italy Quality began to define a list of involved vehicles based on supplier records.

• As of November 9, 2020, FCA US LLC ("FCA US") has identified zero customer assistance records, zero warranty claims, and zero field reports potentially relating to this issue.

- As of November 9, 2020, FCA US is not aware of any accidents or injuries potentially relating to this issue.
- On November 10, 2020, FCA Italy determined, through the Vehicle Regulations Committee, to conduct a voluntary safety recall of the affected vehicles.

Description of Remedy :

Description of Remedy Program :	FCA US will conduct a voluntary safety recall on all affected vehicles to replace the rear brake discs.	
	FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.	
How Remedy Component Differs from Recalled Component :	The remedy component will be a rear brake disc that utilizes a new running in process.	
Identify How/When Recall Condition was Corrected in Production :	NR	
Recall Schedule :		
Description of Recall Schedule :	**11/18/2020: FCA US will notify dealers and begin notifying owners on or about 01/07/2021.	
Planned Dealer Notification Date :	JAN 07, 2021 - JAN 07, 2021	
Planned Owner Notification Date : JAN 07, 2021 - JAN 07, 2021		

* NR - Not Reported