

# Part 573 Safety Recall Report

# 20V-719

**Manufacturer Name :** Newmar Corporation**Submission Date :** NOV 20, 2020**NHTSA Recall No. :** 20V-719**Manufacturer Recall No. :** 20E 071**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

**Population :**

Number of potentially involved : 710

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2019-2020 Newmar Bay Star

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

**Descriptive Information :** On certain motorhomes using the Dometic cooking stove, the saddle valve securing bolt may be overtightened. This could possibly damage the o-ring seal causing a continuous gas leak at the saddle valve to manifold connection. Having a gas leak increases the risk of a fire causing injury. Correction: Dometic will provide repair kits for the stoves at no cost to the customer.

Bay Star= 302

Production Dates : MAY 13, 2019 - NOV 06, 2020

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2019-2019 Newmar Ventana LE

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

**Descriptive Information :** On certain motorhomes using the Dometic cooking stove, the saddle valve securing bolt may be overtightened. This could possibly damage the o-ring seal causing a continuous gas leak at the saddle valve to manifold connection. Having a gas leak increases the risk of a fire causing injury. Correction: Dometic will provide repair kits for the stoves at no cost to the customer. Ventana LE= 2

Production Dates : MAY 13, 2019 - NOV 06, 2020

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2019-2020 Newmar Ventana

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes using the Dometic cooking stove, the saddle valve securing bolt may be overtightened. This could possibly damage the o-ring seal causing a continuous gas leak at the saddle valve to manifold connection. Having a gas leak increases the risk of a fire causing injury. Correction: Dometic will provide repair kits for the stoves at no cost to the customer. Ventana= 27

Production Dates : MAY 13, 2019 - NOV 06, 2020

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 4 : 2020-2020 Newmar Canyon Star

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes using the Dometic cooking stove, the saddle valve securing bolt may be overtightened. This could possibly damage the o-ring seal causing a continuous gas leak at the saddle valve to manifold connection. Having a gas leak increases the risk of a fire causing injury. Correction: Dometic will provide repair kits for the stoves at no cost to the customer. Canyon Star= 130

Production Dates : MAY 13, 2019 - NOV 06, 2020

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 5 : 2020-2020 Newmar Dutch Star

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes using the Dometic cooking stove, the saddle valve securing bolt may be overtightened. This could possibly damage the o-ring seal causing a continuous gas leak at the saddle valve to manifold connection. Having a gas leak increases the risk of a fire causing injury. Correction: Dometic will provide repair kits for the stoves at no cost to the customer. Dutch Star= 4

Production Dates : MAY 13, 2019 - NOV 06, 2020

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 6 : 2020-2020 Newmar Kountry Star

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes using the Dometic cooking stove, the saddle valve securing bolt may be overtightened. This could possibly damage the o-ring seal causing a continuous gas leak at the saddle valve to manifold connection. Having a gas leak increases the risk of a fire causing injury. Correction: Dometic will provide repair kits for the stoves at no cost to the customer. Kountry Star= 181

Production Dates : MAY 13, 2019 - NOV 06, 2020

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 7 : 2020-2020 Newmar Super Star

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes using the Dometic cooking stove, the saddle valve securing bolt may be overtightened. This could possibly damage the o-ring seal causing a continuous gas leak at the saddle valve to manifold connection. Having a gas leak increases the risk of a fire causing injury. Correction: Dometic will provide repair kits for the stoves at no cost to the customer. Super Star= 2

Production Dates : MAY 13, 2019 - NOV 06, 2020

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 8 : 2021-2021 Newmar Bay Star Sport

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes using the Dometic cooking stove, the saddle valve securing bolt may be overtightened. This could possibly damage the o-ring seal causing a continuous gas leak at the saddle valve to manifold connection. Having a gas leak increases the risk of a fire causing injury. Correction: Dometic will provide repair kits for the stoves at no cost to the customer. Bay Star Sport= 62

Production Dates : MAY 13, 2019 - NOV 06, 2020

VIN Range 1 : Begin : NR End : NR  Not sequential

## Description of Defect :

Description of the Defect : saddle valve securing bolt may be overtightened. This could possibly damage the o-ring seal causing a continuous gas leak at the saddle valve to manifold connection.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : On certain motorhomes using the Dometic cooking stove, the saddle valve securing bolt may be overtightened. This could possibly damage the o-ring seal causing a continuous gas leak at the saddle valve to manifold connection. Having a gas leak increases the risk of a fire causing injury.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

## Involved Components :

Component Name 1 : NR

Component Description : Dometic propane gas stove

Component Part Number : Models---R1731 & R2131 & S31

## Supplier Identification :

### Component Manufacturer

Name : Dometic

Address : 5155 Verdant Dr.  
Elkhart INDIANA 46516

Country : United States

## Chronology :

On 11/13/2020, Newmar was notified by Dometic of a potential defect on the cooking stove. Today, 11/20/2020, Newmar is giving notice to NHTSA.

## Description of Remedy :

Description of Remedy Program : Dometic will provide Repair Kits for the stoves.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : On or before 01/19/2021, Newmar will send out customer/dealer letters.

Planned Dealer Notification Date : JAN 19, 2021 - JAN 19, 2021

Planned Owner Notification Date : JAN 19, 2021 - JAN 19, 2021

\* NR - Not Reported