

**Recall Annual Report****20V-391****Manufacturer Name :** Airstream, Inc.**NHTSA Recall No. / MFR Recall No. :** 20V-391 /**Recall Subject :** Bolts Securing Suspension Spring May Be Too Long**Owner Notification Beginning Date :** AUG 26, 2020**Owner Notification End Date:** AUG 26, 2020**Annual Reports**

Report #	Submission Date	Reporting Period	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	OCT 25, 2023	2022-3 to 2023-2	145	110	0	0

**Quarterly Reports**

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	JUL 27, 2022	2022-2	145	110	0	0
7	APR 29, 2022	2022-1	145	110	0	0
6	JAN 27, 2022	2021-4	145	110	0	0
5	OCT 28, 2021	2021-3	145	110	0	0
4	AUG 04, 2021	2021-2	145	107	0	0
3	APR 27, 2021	2021-1	145	107	0	0
2	FEB 01, 2021	2020-4	145	105	0	0
1	OCT 28, 2020	2020-3	35	11	0	0

This Document Last Updated : NOV 16, 2023

**Definitions :**

**Reporting Period:** The reporting period is the manufacturer is reporting recall completion figures.

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.